

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Adams Memorial Hospital 1100 Mercer Avenue Decatur, IN 46733 REPORT NUMBER(S) 2016001	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
---	---

3. DOCKET NUMBER(S) 030-31518	4. LICENSE NUMBER(S) 13-26133-01	5. DATE(S) OF INSPECTION Oct. 19, 2016
--------------------------------------	---	---

6. INSPECTION PROCEDURES USED 87130	7. INSPECTION FOCUS AREAS 03.01 - 03.07
--	--

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 02120	2. PRIORITY 3	3. LICENSEE CONTACT John Pasalich, M.D., RSO	4. TELEPHONE NUMBER (877) 317-5811
---------------------------------	----------------------	---	---

<input checked="" type="checkbox"/> Main Office Inspection	Next Inspection Date: <u>Oct. 19, 2019</u>
<input type="checkbox"/> Field Office Inspection	_____
<input type="checkbox"/> Temporary Job Site Inspection	_____

PROGRAM SCOPE

This was a routine inspection of a small community hospital authorized to use byproduct material in 10 CFR 35.100, 35.200 and 35.300. The licensee staffed its nuclear medicine department with one full-time and one part-time technologists who performed studies daily. The department administered approximately 80 patient studies per month which included a full spectrum of procedures. The licensee received its material in unit dose form and bulk from a licensed radiopharmacy. Although authorized on the license, the hospital had not administered any Section 35.300 material since 2012. The hospital retained the services of a consultant who performed quarterly audits of the radiation safety program (last 10/10/2016, with no findings).

This inspection consisted of interviews with licensee personnel, a review of selected records, a tour of the nuclear medicine department, and independent measurements. The inspection included observations of dose calibrator QA checks, security of licensed material, inventories of sealed sources, and use of personnel monitoring. The inspector observed the licensee personnel prepare, assay and administer one unit dose for a cardiac exercise testing procedure.

No violations of NRC requirements were identified during this inspection.