



**KHNP**

**KOREA HYDRO & NUCLEAR POWER CO., LTD**

70-1312-gil, Yuseong-daero, Yuseong-gu, Daejeon, 305-343, KOREA

Tel: +82-42-870-5400 / Fax: +82-42-870-5449

<http://www.khnp.co.kr>

November 15, 2016  
Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555-0001

Attention: Mr. Jeff Ciocco  
Division of New Reactor Licensing

Docket No. 52-046  
MKD/NW-16-1106L

**Subject: Revised Response to RAI 319-8360 for Question 03.09.03-2 (Rev. 2)**

**References: 1) NRC Request for Additional Information 319-8360, dated November 24, 2015**  
**2) KHNP Letter MKD/NW-16-0716L, Response to RAI 319-8360 for Question 03.09.03-2, dated July 6, 2016**  
**3) KHNP Letter MKD/NW-16-0908L, Revised Response to RAI 319-8360 for Question 03.09.03-2, dated August 19, 2016**

KHNP is hereby submitting a revised response to RAI 319-8360, dated November 24, 2015. The revised response addresses Question 03.09.03-2 to clarify that piping loads due to internal pressure are not transferred to their associated supports. The enclosure provides the revised response to RAI 319-8360 for Question 03.09.03-2 (Rev. 2) (Non-Proprietary).

If additional information or clarification is required, please contact Daegeun Ahn, Director of KHNP Washington DC Center at [ahn.daegeun@khnp.co.kr](mailto:ahn.daegeun@khnp.co.kr) or 703-388-0592.

Sincerely,

Jae-yong Lee  
Project Manager  
Advanced Reactors Development Laboratory  
Korea Hydro and Nuclear Power Co., Ltd

Enclosure: Revised Response to RAI 319-8360 for Question 03.09.03-2 (Rev. 2) (Non-Proprietary)

**Enclosure**

Revised Response to RAI 319-8360 for Question 03.09.03-2 (Rev. 2)

(Non-Proprietary)

November 15, 2016