ent a st	ATTACHED IS PART 21 REP	ORT FROM. IE MAIL UNIT - ROOM 317 E/	/₩	
	PART 21 IDENTIFICATION NO.	COMPANY NAME	acific Hast Electric	
•	78-044-00 2 DATE OF LETTER 12/7/78	DATE DISTRIBUT	- <u>27,75,523</u> TED	
•	ORIGINAL REPORT X SUPPLEMENTARY			
*	DISTRIBUTION: REACTOR(R)	FUEL CYCLE AND MATERIALS(M)	SAFEGUARDS(S)	
	NRR/DOR (Stello)	NMSS/FC&MS	NRR/DOR (Stello)	
	NRR/DPM (Boyd)	AD/FF&MSI	NMSS/SG	
•	AD/ROI (Sniezek/Seyfrit)	PDR .	AD/SG-IE	
	AD/RCI	MPA/PERFORMANCE EVALUATION BR.	AD/ROI	
	MPA/PERFORMANCE EVALUATION BR MNB 12105 REGIONS	MNB 12105 REGIONS	REGIONS	
		NSIC -	MPA/PERFORMANCE EVAL-	
	PDR	TIC	UATION BR. MNB1210 PDR	
	LPDR	IE FILES (2)	LPDR	
	NSIC	CENTRAL FILES-SS 396	NSIC	
	TIC	CENTRAL FILES (CHRON)	TIC	
	IE FILES (2)		IE FILES (2)	
. (CENTRAL EILES 016		CENTRAL FILES 016	
. •	CENTRAL FILES (CHRON)		CENTRAL FILES (CHRON)	
	ACTION:	•	CENTRAL FILES - SS 398	
	<u>101408</u> .		•	

.

1

PRELIMINARY EVALUATION OF THE ATTACHED REPORT INDICATES LEAD RESPONSIBILITY FOR FOLLOW-UP AS SHOWN BELOW:

•	IE (RCI) ROI SG	-		<u>NRR</u>	•	<u>NMS</u>	<u>s</u>		
 	FFMS	, <u>,</u>	, ,	· .	•			· · ·	
						می از معدمت میرود و ۲ ۱۰ ماریک (معرومی) مسترد و ۲ ۱۰ ماریک (۲۰ میرومی) مسترد و ۲ ۱۰ ماریک (۲۰ میرومی) ۱۰ ماریک (۲۰ میرومی)		2017 - 2017 - 2017 - 2017 New York - 2017 - 2017 New York - 2017 - 2017 - 2017	- م م

, · · · N N • •

м

٠,

PACIFIC GAS AND ELECTRIC COMPANY

77 BEALE STREET . SAN FRANCISCO, CALIFORNIA 94106

78-044-002

J. DEAN WORTHINGTON EXECUTIVE VICE PRESIDENT

December 7, 1978

Mr. R. H. Engelken, Director Office of Inspection and Enforcement Region V U. S. Nuclear Regulatory Commission

1990 North California Boulevard Walnut Creek Plaza, Suite 202 Walnut Creek, CA 94596

> Re: Docket No. 50-275-OL Docket No. 50-323-OL Diablo Canyon Site, Units 1 and 2

Dear Mr. Engelken:

Our letter dated April 3, 1978, identified a defect in some Unit 2 NEMA Size 2 motor controllers which was deemed reportable in accordance with 10 CFR Part 21.21. Our letter dated August 17, 1978, updated the schedule for completion of this work.

This letter is a further update on completion of this work. Unit 1 inspection is complete and no kick-out spring replacement was necessary. The inspection and replacement, as appropriate, of kick-out springs for Unit 2 will be completed prior to the Unit 2 Hot Functional Testing.

Sincerely, -) D. Worthung Tongs

cc: Director

Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission

Washington, D.C. 20555 (3 copies)

7812210386

•

.

1993:065