

SAFETY INJECTION
ACTUATION SIGNAL VS BREAK AREA




FIGURE 6.2-3
July, 1982