

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8904190300 DOC. DATE: 89/04/10 NOTARIZED: NO DOCKET #
 FACIL: 50-323 Diablo Canyon Nuclear Power Plant, Unit 2, Pacific Ga 05000323
 AUTH. NAME AUTHOR AFFILIATION
 MENDONCA, M. Region 5, Ofc of the Director
 NARBUT, P. Region 5, Ofc of the Director
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: PNO-V-89-024 on: 890407, shutdown greater than 48 h to repair leaking pressurizer code safety valve.

DISTRIBUTION CODE: IE34D COPIES RECEIVED: LTR 0 ENCL 1 SIZE: 1
 TITLE: Preliminary Notification-Occurrence/Non-Routine Event/Safeguards Even

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
INTERNAL:	ACRS/SIESS	1 1	AEOD/DSP/TPAB	1 1
	NRC OP CNTR	1 1	NRR/DRIS/SGB 9A	1 1
	NRR/DRIS/SIB 9A	1 1	NRR/DRIS/VIB	1 1
	NRR/PMAS/ILRB12	1 1	NUDOCS-ABSTRACT	1 1
	OE LIEBERMAN, J	1 1	<u>REG FILE</u> 02	1 1
	RES BROOKS, B	1 1	RES DEPY	1 1
	RES FILE	1 1	RES/DE	1 1
	RES/DRA	1 1	RES/DSIR	1 1
	RES/DSIR/EIB	1 1	RES/DSR DEPY	1 1
	RES/PMPDAS	1 1	RGN5 FILE 01	1 1
EXTERNAL:	DOE BARBER EV34	1 1	LPDR	1 1
	NRC PDR	1 1	NSIC	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR ~~24~~ ENCL 24

R
I
D
S
/
A
D
S
/
A
D
S
/
A
D
S

This preliminary notification constitutes EARLY notice of events of POSSIBLE safety or public interest significance. The information presented is as initially received without verification or evaluation and is basically all that is known by Region V staff on this date.

FACILITY: PACIFIC GAS & ELECTRIC COMPANY
DIABLO CANYON UNIT 2
DOCKET NO. 50-323
SAN LUIS OBISPO COUNTY, CA

Emergency Classification
 Notification of Unusual Event
 Alert
 Site Area Emergency
 General Emergency
 Not Applicable

SUBJECT: SHUTDOWN GREATER THAN 48 HOURS TO REPAIR A LEAKING PRESSURIZER CODE SAFETY VALVE

On April 7, 1989, at about 8:00 pm PDT, the licensee commenced an orderly shutdown of Unit 2 from 100% power in order to begin an approximate seven day outage to repair a leaking pressurizer code safety valve.

The valve (8010A) had been leaking since March 21, 1989 at an approximate rate of 0.2 gpm with occasional discharges greater than that. The licensee also intends to perform miscellaneous maintenance tasks, the largest of which is to replace about one dozen leaking valves in the condensate system. The licensee's current schedule and progress indicate a return to normal power operations by Friday, April 14, 1989.

The licensee made a press release announcing the shutdown on April 5, 1989.

This information is current as of 9:00 am PDT on April 10, 1989.

CONTACT: N. Mendonca, RV
FTS 463-3720

P. Narbut
805-595-2354

DISTRIBUTION BY 5520:

Date 4/10 Time 11:47 AM
Chairman Zech EDO RI
Comm. Roberts AEOD RII
Comm. Carr PAO RIII
Comm. Rogers SLITP RIV
Comm. Curtiss NRR
CA NMSS
ARM
OGC OI
ACRS OIA
GPA RES
SECY

FAX TO:

Date 4/10 Time 3:45 PM

INPO
NSAC
LICENSEE
RESIDENT INSPECTOR
HQS. OPERATIONS OFFICER
PDR

MAIL TO:

DCS (Original)
DOT:(Trans. Only, Applicable State)

RV FORM 211
Revised: 8/19/87

0/1
54