

REVISED UNIT SHUTDOWNS AND POWER REDUCTIONS
FOR THE MONTH OF AUGUST 1996

9610180192 961011
PDR ADOCK 05000275
R PDR



100

100

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO.: 50-323
 UNIT: 2
 DATE: 10/11/96
 COMPLETED BY: S. D. LaForce
 TELEPHONE: (805) 545-4741

REPORT MONTH: August 1996

NO.	DATE	TYPE ¹	DURATION (HOURS)	REASON ²	METHOD OF SHUTDOWN ³	LICENSEE EVENT REPORT	SYSTEM CODE ⁴	COMPONENT CODE ⁵	CAUSE & CORRECTIVE ACTION TO PREVENT RECURRENCE
1	8/2/96	F	44.6	A	1	N/A	TG	V	An electro-hydraulic fluid leak on main turbine trip solenoid valves due to O-ring degradation. O-ring replaced.
2	8/10/96	F	118.7	H (500 kV system disturbance)	3	1-96-012-00	N/A	N/A	500 kV system disturbance. No corrective actions were deemed necessary.
3	8/18/96	F	N/A	H (Wildland fire near 500 kV system)	5	N/A	N/A	N/A	Wildland fire near 500 kV system. No corrective actions were deemed necessary.



Vertical text or markings on the right side of the page.

Vertical text or markings on the right side of the page.

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO.: 50-323
 UNIT: 2
 DATE: 10/11/96
 COMPLETED BY: S. D. LaForce
 TELEPHONE: (805) 545-4741

REPORT MONTH: August 1996 (cont.)

4	8/21/96	F	N/A	H (Wildland fire near 500 kV system)	5	N/A	N/A	N/A	Wildland fire near 500 kV system. Unit 2 reduced power as a prudent action.
---	---------	---	-----	---	---	-----	-----	-----	---

- | | | | | |
|---|---|---|--|--|
| <p>1
Type:
F-Forced
S-Scheduled</p> | <p>2
Reason:
A-Equipment Failure (Explain)
B-Maintenance or Test
C-Refueling
D-Regulatory Restriction
E-Operator Training & License Examination
F- Administrative
G-Operational Error (Explain)
H-Other (Explain)</p> | <p>3
Method:
1-Manual
2-Manual Scram
3-Automatic Scram
4-Continuation from
previous month
5-Power reduction
6-Other</p> | <p>4
EIS Systems List, Table 1</p> | <p>5
IEEE Std. 803A-1983, "IEEE
Recommended Practice for Unique
Identification in Power Plants and
Related Facilities - Table 2"</p> |
|---|---|---|--|--|

