

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9706040328 DOC. DATE: 97/05/28 NOTARIZED: NO DOCKET #
 FACIL: 50-275 Diablo Canyon Nuclear Power Plant, Unit 1, Pacific Gas 05000275
 AUTH. NAME AUTHOR AFFILIATION
 POWERS, R.P. Pacific Gas & Electric Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards LER 96-011-01, regarding fire barrier penetration seals potentially being outside plant design basis due to untested application of epoxy grout matl & identifies root cause of event.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+7
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD4-2 PD	1 1	BLOOM, S	1 1
INTERNAL:	ACRS	1 1	AEOD/SPD/RAB	2 2
	AEOD/SPD/RRAB	1 1	<u>FILE CENTER</u>	1 1
	NRR/DE/ECGB	1 1	NRR/DE/EELB	1 1
	NRR/DE/EMEB	1 1	NRR/DRCH/HHFB	1 1
	NRR/DRCH/HICB	1 1	NRR/DRCH/HOLB	1 1
	NRR/DRCH/HQMB	1 1	NRR/DRPM/PECB	1 1
	NRR/DSSA/SPLB	1 1	NRR/DSSA/SRXB	1 1
	RES/DET/EIB	1 1	RGN4 FILE 01	1 1
EXTERNAL:	L ST LOBBY WARD	1 1	LITCO BRYCE, J H	1 1
	NOAC POORE, W.	1 1	NOAC QUEENER, DS	1 1
	NRC PDR	1 1	NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:
 PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 25 ENCL 25

C
A
T
E
G
O
R
Y

1

D
O
C
U
M
E
N
T

Pacific Gas and Electric Company

Diablo Canyon Power Plant
P.O. Box 56
Avila Beach, CA 93424
805/545-6000

Robert P. Powers
Vice President-Diablo Canyon
Operations and Plant Manager

May 28, 1997

PG&E Letter DCL-97-094



U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

Docket No. 50-275, OL-DPR-80
Docket No. 50-323, OL-DPR-82
Diablo Canyon Units 1 and 2
Licensee Event Report 1-96-011-01
Fire Barrier Penetration Seals Outside Design Basis Due to an Untested
Application of Epoxy Grout Material

Dear Commissioners and Staff:

PG&E is submitting the enclosed revision to Licensee Event Report (LER) 1-96-011 regarding fire barrier penetration seals potentially being outside the plant design basis due to an untested application of epoxy grout material. This revision is submitted to identify the root cause of the event and the corrective actions to prevent recurrence. Changes to the LER are noted by revisions in the right margin.

The health and safety of the public were not adversely affected by this condition.

Sincerely,

A handwritten signature in cursive script, appearing to read 'R. P. Powers'.


Robert P. Powers

cc: Steven D. Bloom
Ellis W. Merschoff
Kenneth E. Perkins
Michael D. Tschiltz
Diablo Distribution
INPO

040006

Enclosure

GRC/2246/N0001995



9706040328 970528
PDR ADDCK 05000275
S PDR

TE 10/1

