

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9809010175 DOC.DATE: 98/08/21 NOTARIZED: NO DOCKET #
FACIL:50-275 Diablo Canyon Nuclear Power Plant, Unit 1, Pacific Ga 05000275
AUTH.NAME AUTHOR AFFILIATION
WOMACK,L.F. Pacific Gas & Electric Co.
RECIP.NAME RECIPIENT AFFILIATION
Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 98-009-00, voluntary LER re turbine building siding structural supportd that did not meet all design requirements for tornado wind load resistance.No new commitments made within ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1+7
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

Table with columns: RECIPIENT ID CODE/NAME, COPIES (LTTR, ENCL), RECIPIENT ID CODE/NAME, COPIES (LTTR, ENCL). Rows include INTERNAL and EXTERNAL recipients like ACRS, AEOD/SPD/RRAB, NRR/DE/ECGB, etc.

C
A
T
E
G
O
R
Y
1
D
O
C
U
M
E
N
T

NOTE TO ALL "RIDS" RECIPIENTS: PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083



1

Y

Pacific Gas and Electric Company

245 Market Street, Room 836-N9B
San Francisco, CA 94105

Mailing Address
Mail Code N9B
P.O. Box 770000
San Francisco, CA 94177
415/973-0600 Fax 415/973-6567

Lawrence F. Womack
Vice President
Nuclear Technical Services

August 21, 1998



PG&E Letter DCL-98-106

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555

Docket No. 50-275, OL-DPR-80
Docket No. 50-323, OL-DPR-82
Diablo Canyon Units 1 and 2
Licensee Event Report 1-1998-009-00
Voluntary - Turbine Building Siding Structural Supports Did Not Meet Design
Requirements for Tornado Wind Load Resistance

Dear Commissioners and Staff:

In accordance with guidance provided in NUREG-1022, Revision 1, Section 2.9, PG&E is submitting the enclosed voluntary licensee event report regarding Turbine Building siding structural supports that did not meet all design requirements for tornado wind load resistance.

This event did not adversely affect the health and safety of the public.

Sincerely,

Lawrence F. Womack

cc: Steven D. Bloom
Dennis F. Kirsch
Ellis W. Merschoff
David L. Proulx
Diablo Distribution
INPO

Enclosure

DDM/2246/N0002047

9809010175 980821
PDR ADDCK 05000275
S PDR L

1/1
Ic22



1
4