NRC FORM 591M PART 1 (07-2012)*		U.S. NUCLEAR REGULATORY COMMISSION			
10 CFR 2.201	ETY INSPECTION REPOR	T AND COMPLIANCE II	NSPECTION		
 LICENSEE/LOCATION INSPECTED: Spectrum Techniques, Inc. 106 Union Valley Road Oak Ridge, TN 37830 		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 2100 Renaissance Blvd, Suite 100 King of Prussia, Pennsylvania 19406-2713			
REPORT NUMBER(S)	2016001				
3. DOCKET NUMBER(S) 03034126	4. LICENSE NUMBER 41-23845-01E	R(S)	5. DATE(S) OF INSPE 11/22/201		
LICENSEE:					
 The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regresentative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: 					
	Statement of (Corrective Actions			
I hereby state that, within 30 days, the corrective actions is made in accordar date when full compliance will be achi	e actions described by me to the In nce with the requirements of 10 CF	spector will be taken to correct R 2.201 (corrective steps alreat	ady taken, corrective ste	ps which will be taken,	
Title	Printed Name		Signature	Date	
LICENSEE'S REPRESENTATIVE					
NRC INSPECTOR	R. C. Ragland		/RA/	12/9/2016	
BRANCH CHIEF	B. Welling		/RA/	12/12/2016	
*NRC FORM 591M PART 1 (07-2012) (RI Rev. 09/12/2013) G:\W	ordDocs\Current\Insp Record\I	R41-23845-01E.201600	1.591M-Part1.doc	

SUNSI Review Completed By:	/ RA /	R. C. Ragland
	, , , , , ,	rt. O. rtagiaria

x Public x

x Non-Sensitive