70-1312-gil, Yuseong-daero, Yuseong-gu, Daejeon, 305-343, KOREA Tel: +82-42-870-5400 / Fax: +82-42-870-5449 http://www.khnp.co.kr

January 4, 2017 Document Control Desk U.S. Nuclear Regulatory Commission Washington, DC 20555-0001

Attention: Mr. Jeff Ciocco

Docket No. 52-046

Division of New Reactor Licensing

MKD/NW-16-1180L

Subject: Revised Response to RAI 176-8089 for Question 03.11-11 (Rev. 2)

References: 1) NRC Request for Additional Information 176-8089, dated August 31, 2015

- 2) KHNP Letter MKD/NW-16-0333L, Response to RAI 176-8089 for Question 03.11-11, dated April 12, 2016
- 3) KHNP Letter MKD/NW-16-0842L, Revised Response to RAI 176-8089 for the Question 03.11-11, dated August 4, 2016

KHNP is hereby submitting a revised response to RAI 176-8089, dated August 31, 2015. The revised response addresses Question 03.11-11 to provide additional description for the ESF component leakage.

The enclosure contains the revised response to RAI 176-8089 for Question 03.11-11 (Rev. 2) (Non-Proprietary).

If additional information or clarification is required, please contact Daegeun Ahn, Director of KHNP Washington DC Center at ahn.daegeun@khnp.co.kr or 703-388-0592.

Sincerely,

Jae-yong Lee

Director

Advanced Reactors Development Laboratory

Korea Hydro & Nuclear Power Co., Ltd.

Enclosure: Revised Response to RAI 176-8089 for Question 03.11-11 (Rev. 2) (Non-Proprietary)



Enclosure

Revised Response to RAI 176-8089 for Question 03.11-11 (Rev. 2)

(Non-Proprietary)

January 4, 2017