



REGULATORY OPERATIONAL REPORT COMPLETION

TELETYPE MESSAGE

TO: 015-337-5774 FROM: 015-343-260 X 1342 DATE/TIME 5/23/79 / 3:25p
 Telephone Number Telephone Number
94-7359

TO: RONALD M. GRIGG Director of Regulatory Operation
 USNRC Region I
 631 Park Avenue
 King of Prussia, PA. 19406

From: Niagara Mohawk Power Corporation
 One Mile Point Nuclear Station
 Unit #1
 P.O. Box #32
 Lyncburg, New York 13093

SUBJECT: PROMPT REPORTABLE OCCURRENCE
 BUCKET NO. 50-220 LICENSE NO. DPE-63
 ASSIGNED LER NO. 79-12

EVENT DATE: 5/23/79 REPORT DATE: _____

EVENT DESCRIPTION:

During inspection, a number of concrete anchor bolts were found to be loose or improperly installed.

COMPONENTS INVOLVED:

Concrete Anchor Bolts

CAUSE AND CORRECTIVE ACTION:

A pull-test program has been implemented and deficiencies will be repaired or replaced. Loose bolts are being tightened during inspection

FACILITY STATUS:

NORMAL _____

- | | |
|----------------------------|-------------------------|
| c) Routine Startup _____ | g) Shutdown _____ |
| d) Routine Shutdown _____ | h) Refueling _____ X |
| e) Steady State Oper _____ | i) Other _____ |
| f) Load Change _____ | j) Not Applicable _____ |

A written follow-up report will be sent within two weeks.

TELETYPE TO R.H. Grier FROM T.J. Perkins DATE 5/23/79
DATE DATE
R.R. Schneider

7906010214

Acc 5/10

54