

June 12, 1979

Mr. Boyce H. Grier  
Director  
United States Nuclear Regulatory Commission  
Region I  
631 Park Avenue  
King of Prussia, PA. 19406


RE: Docket No. 50-220

Dear Mr. Grier:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specifications, we hereby submit Licensee Event Report LER 79-13, which is in accordance with Section 6.9.2b(3) of the Technical Specifications.

This report has been completed in the format designated in NUREG-0161, dated July 1977.

Very truly yours,

  
R.R. Schneider  
Vice President -  
Electric Production

mtm

Attachment (3 copies)

xc: Director, Office of I&E (30 copies)  
Director, Office of MIPC (3 copies)

7906180 487

A002  
5 1/1

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	N	M	P	1	0	0	-	0	0	0	0	0	0	0	0	0	4	1	1	1	1	4	5		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33		
LICENSEE CODE														LICENSE NUMBER						LICENSE TYPE					CAT 58			

0	1	L	0	5	0	0	0	2	2	0	0	5	2	5	7	9	0	6	1	2	7	9	9		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
CON'T		REPORT SOURCE		DOCKET NUMBER										EVENT DATE					REPORT DATE						

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During refueling outage, it was noted that the Site Operations Review

0 3 | Committee failed to review temporary changes to three Instrument

0 4 | Surveillance Procedures within the seven days as required by Technical

0 5 | Specifications. This resulted in minimal safety implications.

0 6 |

0 7 |

0 8 |

0	9	Z	Z	X	X	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	0	1	3	0	3	L	Z	Z	9	9	9	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE		LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Three Instrument Surveillance Procedure temporary changes were not

1 1 | reviewed by the Site Operations Review Committee within seven days. The

1 2 | review has since taken place and approvals have been received.

1 3 |

1 4 |

1	5	H	0	0	0	NA	Z	NA	
7	8	9	10	11	12	13	14	15	
FACILITY STATUS		% POWER			OTHER STATUS			METHOD OF DISCOVERY	
ACTIVITY RELEASED		CONTENT OF RELEASE			AMOUNT OF ACTIVITY			LOCATION OF RELEASE	
PERSONNEL EXPOSURES		NUMBER			TYPE			DESCRIPTION	
PERSONNEL INJURIES		NUMBER			TYPE			DESCRIPTION	
LOSS OF OR DAMAGE TO FACILITY		TYPE			DESCRIPTION				
PUBLICITY ISSUED		DESCRIPTION							

7906180492

NAME OF PREPARER E. Duda

PHONE: (315)343-2110 Ext 1306