

NIAGARA MOHAWK POWER CORPORATION

TELECOPY MESSAGE

TO: 015-337-5329 Telephone Number 84-7359 FROM: 015-343-240 X 1312 Telephone Number DATE/TIME 5/23/79 3:25p

TO: ROWEN H. GRIER Director of Regulatory Operations USNRC Region I 601 Park Avenue King of Prussia, PA. 19406 FROM: Niagara Mohawk Power Corporation One Mile Point Nuclear Station Unit #1 P.O. Box #32 Lycoming, New York 13093

SUBJECT: PROMPT REPORTABLE OCCURRENCE BUCKET NO. 58-220 LICENSE NO. DPE-63 ASSIGNED LER NO. 79-12

EVENT DATE: 5/23/79 REPORT DATE:

EVENT DESCRIPTION: During inspection, a number of concrete anchor bolts were found to be loose or improperly installed.

COMPONENTS INVOLVED: Concrete Anchor Bolts

CAUSE AND REMEDIAL ACTION: A pull-test program has been implemented and deficiencies will be repaired or replaced. Loose bolts are being tightened during inspection

FACILITY STATUS: 2 THEORETICAL RUN c) Routine Startup d) Routine Shutdown e) Steady State Oper f) Load Change g) Shutdown h) Refueling X i) Other j) Not Applicable

A written follow-up report will be sent within two weeks.

TELECOPY TO R.H. Grier R.R. Schneider FROM T.J. Peckins DATE 5/23/79

