

NIAGARA MOHAWK POWER CORPORATION/300 ERIE BOULEVARD WEST, SYRACUSE, N.Y. 13202/TELEPHONE (315) 474-1511

August 10, 1979

Mr. Boyce H. Grier
Director
United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA. 19406

RE: Docket No. 50-220

Dear Mr. Grier:

In accordance with Nine Mile Point Nuclear Station Unit #1 Technical Specifications, we hereby submit the Licensee Event Report LER 79-18, which is in accordance with Section 6.9.2b(1) of the Technical Specifications.

This report has been completed in the format designated in NUREG-0161, dated July 1977.

Very truly yours,



T.E. Lempges
General Superintendent
Nuclear Generation
for R.R. Schneider
Vice President -
Electric Production

mtm

Attachment (3 copies)

xc: Director, Office of I&E (30 copies)
Director, Office of MIPC (3 copies)

790814 0651

A002
5/11

LICENSEE EVENT REPORT

CONTROL BLOCK:

							(1)
--	--	--	--	--	--	--	-----

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	N	M	P	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	1	4			5
7	8	LICENSEE CODE						14	LICENSE NUMBER										25	LICENSE TYPE					30	57	CAT	58		

CON'T

REPORT SOURCE 7 8 60 61 68 69 74 75 80

DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During steady state operation, a vacuum switch, 68-12B, in the Vacuum
0 3 | Relief System, failed to open at its proper setpoint. This resulted in
0 4 | minimal safety implications.
0 5 |
0 6 |
0 7 |
0 8 |

SYSTEM CODE S D		CAUSE CODE E		CAUSE SUBCODE E		COMPONENT CODE I N S T R U						COMP. SUBCODE S		VALVE SUBCODE Z	
EVENT YEAR 7 9			SEQUENTIAL REPORT NO. 0 1 8		<input checked="" type="checkbox"/>	OCCURRENCE CODE 0 3		REPORT TYPE L			REVISION NO. 0				
ACTION TAKEN E	FUTURE ACTION Z	EFFECT ON PLANT Z	SHUTDOWN METHOD Z	HOURS 0 0 0	ATTACHMENT SUBMITTED N	NP&D-4 FORM SUB. N		PRIME COMP. SUPPLIER L		COMPONENT MANUFACTURER M 2 3 5					

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | No cause has been identified for this occurrence, but the switch has been

1 1 | adjusted to open at its proper setpoint.

1 2 |

1 3 |

1 4 |

8 9
FACILITY STATUS 1 5 E 28
% POWER 0 9 0 29 OTHER STATUS 30 NA
METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION 32 Calibration test

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)

1 6 Z (33) Z (34) NA 44 45 80

PERSONNEL EXPOSURES									
NUMBER				TYPE	DESCRIPTION				
1	7	0	0	0	(37) Z	(38) NA	(39)		

PERSONNEL INJURIES					
NUMBER			DESCRIPTION		
0	0	0	(40)	NA	

1		9		Z		NA		42		43	
---	--	---	--	---	--	----	--	----	--	----	--

PUBLICITY (45)
 ISSUED (44) NA
 790814 0655
 NRC USE ONLY

E. Duda

NRC USE ONLY

(315) 343-2110 Ext 1306