

September 6, 1979

Office of Inspection and Enforcement
Region I
Attn: Mr. R. T. Carlson, Chief
Reactor Construction and Engineering
Support Branch
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Dear Mr. Carlson:


Re: Nine Mile Point Unit 2
Docket No. 50-410

Attached is the final report of the deficiency concerning inadequate nondestructive examination performed on the Nine Mile Point Unit 2 containment liner welds. This condition was reported to your staff on May 18, 1979 and May 24, 1979.

In accordance with Title 10, Section 50.55(e) of the Code of Federal Regulations, the final report includes a description of the deficiency, an analysis of the safety implications and the corrective action taken. Based on our evaluation, we have determined that this condition could have been a safety hazard if left uncorrected.

Very truly yours,

NIAGARA MOHAWK POWER CORPORATION


James Bartlett
Executive Vice President

Attachment

Xc: Office of Inspection and Enforcement
Washington, D. C. 20555

7910170 008

