

TELECOPY MESSAGE

50:20

TO: 215-331-5324 FROM: 215-343-2400 DATE/TIME 9/19/79
 Telephone Number Telephone Number

84-1359

TO: ROYCE M. GIER
 Director of Regulatory Operations
 USNRC Region I
 631 Park Avenue
 King of Prussia, PA 19406

From: Niagara Mohawk Power Corporation
 Nine Mile Point Nuclear Station
 Unit #1
 P.O. Box #32
 Lycoming, New York 13090

SUBJECT: PROPOSED REPAIRS TO CONTAINMENT SPRAY SYSTEM
 DOCKET NO. 50-220 LICENSE NO. DPR-63
 ASSIGNED LER NO. 79-22

EVENT DATE: 9/18/79 REPORT DATE: 9/19/79

EVENT DESCRIPTION:
 Found one seismic component on containment spray system outside
 the primary containment was not installed as required by construction
 drawings.

COMPONENTS INVOLVED: Seismic component 80-9C-28

CAUSE AND REMEDIAL ACTION:

Not installed at construction. Installed design and order to install
 component. Remedial applicable: containment spray loop inoperable.
 Performing redundant loop sprayability test as required by Technical
 Specifications.

FACILITY STATUS:

% THERMAL HM: 94%

- c) Routine Startup
- d) Routine Shutdown
- e) Steady State Oper X
- f) Load Change

- a) Shutdown
- b) Refueling
- c) Other
- d) Not Applicable

A written follow-up report will be sent within two weeks.

CCP

TELECOPY TO B.H. Gier FROM: T.E. Lempers DATE 9/19/79
 Name Name
R.L. Schneider T.E. Lempers 9/19/79

