



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
631 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19406

JAN 4 1980

Docket No. 50-220

Niagara Mohawk Power Corporation
ATTN: Mr. R. R. Schneider
Vice President
Electric Operations
300 Erie Boulevard West
Syracuse, New York 13202


Gentlemen:

NRC review of your Bulletin 79-14 responses dated November 7, 1979 and December 7, 1979 which provide an update schedule for completion of Bulletin 79-14 requirements has been completed. Based on this review and a telephone conversation between Mr. Baunack of this office and Mr. Perkins of your staff on December 20, 1979, we understand that the following will be accomplished:

- a. The remaining inspections required by Bulletin 79-14 will be completed before March 31, 1980.
- b. A report will be submitted with the final results of the inspection within 30 days of the completions of the inspection.
- c. If the seismic qualification of any safety system piping or component is shown to be improper, the plant will be placed in the cold shutdown condition either within 7 days of identification of any such uncorrected item or as specified in Technical Specifications, whichever is less.
- d. Should such a shutdown (Item c. above) occur, the facility will remain in the cold shutdown condition until corrective action on the identified component is completed.

If our understanding of your planned action described above is not in accordance with your actual plans and actions being implemented, please contact this office by telephone or in writing within 24 hours of receipt of this letter.

Sincerely,


Boyce H. Grier
Director

cc:
T.J. Perkins, Station Superintendent

Q 8002050233 A02

