

NIAGARA MOHAWK POWER CORPORATION

TELECOPY MESSAGE

TO: 215-337-5324 FROM: 315-343-2110 X1376 DATE/TIME July 16, 1980 11:40 a.m.  
Telephone Number Telephone Number

TO: BOYCE H. GRIER From: Niagara Mohawk Power Corporation  
Director of Regulatory Operation Nine Mile Point Nuclear Station  
USNRC Region I Unit #1  
631 Park Avenue P.O. Box #32  
King of Prussia, PA. 19406 Lycoing, New York 13093

SUBJECT: PROMPT REPORTABLE OCCURRENCE  
DOCKET NO. 50-220 LICENSE NO. DPR-63  
ASSIGNED LER NO. 80-13

EVENT DATE: 7/15/80 REPORT DATE: 7/15/80

EVENT DESCRIPTION:  
CRD 34-43 did not scram during manual scram test for  
I.E. Bulletin 80-17.

COMPONENTS INVOLVED:  
Scram Solenoid Valve

CAUSE AND REMEDIAL ACTION:  
Caused by valve plunger sticking, apparently due to presence  
of internal corrosion and moisture. The solenoid valve was  
cleaned and reassembled.

FACILITY STATUS: ~~\_\_\_\_\_~~ X THERMAL MIL 7.8  
c) Routine Startup \_\_\_\_\_ g) Shutdown X  
d) Routine Shutdown \_\_\_\_\_ h) Refueling \_\_\_\_\_  
e) Steady State Oper \_\_\_\_\_ i) Other \_\_\_\_\_  
f) Load Change \_\_\_\_\_ j) Not Applicable \_\_\_\_\_

A written follow-up report will be sent within two weeks.

TELECOPY TO Boyce H. Grier FROM: Niagara Mohawk DATE July 18, 1980  
NAME NAME



SECRET

SECRET

SECRET

SECRET

SECRET

SECRET

SECRET

SECRET

SECRET

SECRET

SECRET

SECRET

SECRET