



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
631 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19406

August 22, 1980

Docket No. 50-410

Niagara Mohawk Power Corporation
ATTN: Mr. Gerald K. Rhode
Vice President
System Project Management
c/o Miss Catherine R. Seibert
300 Erie Boulevard, West
Syracuse, New York 13202

KDZ

Gentlemen:

The enclosed Supplement No. 3 to IE Bulletin No. 80-17, "Failure of 76 of 185 Control Rods to Fully Insert During a Scram at a BWR," is forwarded to you for information. No written response is required. If you desire additional information regarding this matter, please contact this office.

Sincerely,

Boyce H. Grier
Boyce H. Grier
Director

Enclosures:

1. Supplement No. 3 to IE Bulletin No. 80-17
2. List of Recently Issued IE Bulletins

CONTACT: D. L. Capton
(215-337-5266)

cc w/encls:
Eugene B. Thomas, Jr., Esquire

8009120095

Q

R

