

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8012040438 DOC. DATE: 80/11/26 NOTARIZED: NO DOCKET #
 FACIL: 50-220 Nine Mile Point Nuclear Station, Unit 1, Niagara Powe 05000220
 AUTH. NAME: AUTHOR AFFILIATION
 DISE, D.P. Niagara Mohawk Power Corp.
 RECIP. NAME: RECIPIENT AFFILIATION
 IPPOLITO, T.A. Operating Reactors Branch 2

SUBJECT: Informs that licensee plans to install Class IEI protection sys by Spring 1983. refueling outage to meet requirements per 800924 ltr. Design info & proposed Tech Specs will be provided prior to refueling outage.

DISTRIBUTION CODE: A001S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: General Distribution for after Issuance of Operating License

NOTES:

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTR	ENCL		LTR	ENCL
	IPPOLITO, T. 04	13	15			
INTERNAL:	D/DIR, HUM FAC 08	1.	1	I&E	06	2
	NRC PDR 02	1.	1	DELO	11.	1
	OR ASSESS BR 10	1.	1	REG. FILE	01.	1
EXTERNAL:	ACRS 09	16	1	LPDR	03	1
	NSIC 05	1.	1			

DEC 5 1980

TOTAL NUMBER OF COPIES REQUIRED: LTR 38 ENCL 0

5L

DEC 2 1980

REGULATORY DOCKET FILE COPY

November 26, 1980

Director of Nuclear Reactor Regulation
Attention: Mr. Thomas A. Ippolito, Chief
Operating Reactors Branch 2
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Gentlemen:

Re: Nine Mile Point Unit 1
Docket No. 50-220
DPR-63

1980 DEC 3 PM 1:01
DISTRIBUTION SERVICES
BRANCH
DISTRIBUTION
SERVICES UNIT

In our letter of January 14, 1980 Niagara Mohawk indicated that Class IE alarms would be installed on the reactor protection system motor generator sets by the end of the spring 1981 refueling outage. Your letter of September 24, 1980 indicated that alarms would not be sufficient.

Based on your letter, we do not plan to install alarms on the motor generator sets during the spring 1981 refueling outage. To meet your requirements, we plan to install a Class IE protection system by the spring 1983 refueling outage. Design information and proposed technical specifications will be provided 90 days prior to the beginning of the refueling outage.

In the interim, we will continue the surveillance as outlined in your August 7, 1978 letter.

Very truly yours,

NIAGARA MOHAWK POWER CORPORATION

Donald P. Dise
Donald P. Dise
Vice President Engineering

MGM:ja

8012040438

P

4001
5
110

19.

2000

21

22