

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8102120037 DOC. DATE: 81/01/16 NOTARIZED: NO DOCKET #  
 FACIL: 50-220 Nine Mile Point Nuclear Station, Unit 1, Niagara Powe 05000220  
 AUTH. NAME AUTHOR AFFILIATION  
 LEMPGES, T.E. Niagara Mohawk Power Corp.  
 RECIP. NAME RECIPIENT AFFILIATION  
 Office of Management and Program Analysis

SUBJECT: Forwards list of mods installed or completed during 1980.  
 List inadvertently omitted from 801231 "Rept of Operating  
 Statistics & Shutdown Experience." Rept will be made part of  
 monthly operations rept.

DISTRIBUTION CODE: A008S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2  
 TITLE: Annual, Semi-Annual & Monthly Operating Reports (OL Stage)

NOTES:

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL		ID CODE/NAME	LTR
	IPPOLITO, T. 04	7	1			
INTERNAL:	D/DIR, HUM FAC07	1	1	DIR, DIV OF LIC	1	1
	I&E 06	2	2	MPA 13	2	2
	NRC PDR 02	1	1	OP EX EVAL BR09	1	1
	OR ASSESS BR 10	1	1	<u>REG FILE</u> 01	1	1
EXTERNAL:	ACRS 11	1	1	BROOKHAVEN 12	1	1
	LPDR 03	1	1	NSIC 05	1	1

FEB 17 1981

TOTAL NUMBER OF COPIES REQUIRED: LTR 21 ENCL 0

RB



Faint, illegible text at the top of the page, possibly a header or introductory paragraph.

Main body of faint, illegible text, appearing to be several lines of a document.

Large area of extremely faint, illegible text occupying the bottom half of the page.

January 16, 1981

Director, Office of Management  
Information and Program Control  
United States Nuclear Regulatory Commission  
Washington, D. C. 20555

RE: Docket No. 50-220  
DPR - 63

Gentlemen:

Attached is a copy of the list of modifications which were installed or completed during 1980. This list was inadvertently omitted when the Report of Operating Statistics and Shutdown Experience for December, 1980, was submitted.

In the future this report will be made a regular part of the monthly operating report.

Very truly yours,

Thomas E. Lempges  
Vice President  
Nuclear Generation

TEL:jl  
Attachment  
xc: Director, Office of I&E (10 copies)

A008  
S  
1/0

DISTRIBUTION  
UNIT

1981 FEB 10 PM 4 36

U.S. NUC  
REGULATORY COMMISSION  
BRANCH

P

8102120037

The following modifications were installed and completed during 1980 and are safety-related.

- 79.12 Anticipated Transient Without Scram - Work Package #1  
Reactor Recirc. Pump Trip on High Reactor Pressure and Low-Low Reactor Level
- 80.07 Vent & Purge Valve Mechanical Stops  
Limit opening on containment MOV & AOV isolation valves to 40% stroke
- 80.11 Reroute Cable Power Board 101 to Power Board 103  
Provide separation on cable route of normal supply to P.B. 103 (E.D.G.)
- 80.43 Torus Saddles  
Provide additional support to torus shell
- 80.50 Torus Room Vent Penetrations  
Provide penetrations to torus containment room above flooding level to allow ventilation for 80.43 work
- 80.64 Separate Fuel Oil Lines to Diesel Generators  
Eliminate inner tie on diesel generator fuel supply lines
- 80.70 APRM - LPRM Selection  
Provide additional LPRM selections for APRM's to eliminate failed LPRM chambers from APRM assignment
- 78.34 Fire Protection - Phase 1 and 2  
Structural modifications safety and non-safety related to provide stair towers and area separation for fire protection

A safety analysis was performed for each safety-related modification. For each modification, the probability of occurrence or the possibility a different type of an accident or malfunction than those evaluated in the safety analysis report did not change or were enhanced. Also the margin of safety as defined in the basis of the Technical Specifications did not change.

Based on the above, these modifications did not constitute any unreviewed safety questions.

The following modifications were installed and completed during 1980 and are safety-related.

- 79.12 Anticipated Transient Without Scram - Work Package #1  
Reactor Recirc. Pump Trip on High Reactor Pressure and Low-Low Reactor Level
- 80.07 Vent & Purge Valve Mechanical Stops  
Limit opening on containment MOV & AOV isolation valves to 40% stroke
- 80.11 Reroute Cable Power Board 101 to Power Board 103  
Provide separation on cable route of normal supply to P.B. 103 (E.D.G.)
- 80.43 Torus Saddles  
Provide additional support to torus shell
- 80.50 Torus Room Vent Penetrations  
Provide penetrations to torus containment room above flooding level to allow ventilation for 80.43 work
- 80.64 Separate Fuel Oil Lines to Diesel Generators  
Eliminate inner tie on diesel generator fuel supply lines
- 80.70 APRM - LPRM Selection  
Provide additional LPRM selections for APRM's to eliminate failed LPRM chambers from APRM assignment
- 78.34 Fire Protection - Phase 1 and 2  
Structural modifications safety and non-safety related to provide stair towers and area separation for fire protection

A safety analysis was performed for each safety-related modification. For each modification, the probability of occurrence or the possibility a different type of an accident or malfunction than those evaluated in the safety analysis report did not change or were enhanced. Also the margin of safety as defined in the basis of the Technical Specifications did not change.

Based on the above, these modifications did not constitute any unreviewed safety questions.



11-11-11

2"

4

•

•

•

•