


April 7, 1981

Office of Inspection and Enforcement
Region I
Attention: Mr. B. H. Grier, Director
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406



Dear Mr. Grier:

Re: Nine Mile Point Unit 2
Docket No. 50-410

Your June 27, 1980 I. E. Bulletin No. 80-16 requested information regarding the potential misapplication of Rosemount, Inc. Model 1151 and 1152 pressure transmitters in safety related application at Nine Mile Point Unit 2. A preliminary review has identified the potential applications and locations of the suspect parts in safety related systems at Unit 2, as indicated in Table 1 attached.

As indicated in the attached table, the recommended fix is to replace "A" or "D" output boards with "E" output boards. The panels identified in the attached table will be inspected to determine which output boards have been installed. The results of this inspection and the corrective action taken will be reported to you by December 31, 1981.

Very truly yours,

NIAGARA MOHAWK POWER CORPORATION


Gerald K. Rhode
Vice President

System Project Management

PEF:ja

xc: Office of Inspection and Enforcement
Division of Reactor Construction Inspection
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Q 8105060270



NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT UNIT 2
DOCKET NO. 50-410

TABLE 1

RESPONSE TO I.E. BULLETIN 80-16
POTENTIAL MISAPPLICATION OF
ROSEMOUNT PRESSURE TRANSMITTERS

<u>System No. (Name)</u>	<u>Panel Location</u>	<u>Type of Output Board</u>	<u>Fix</u>
B22-N067 (Nuclear Boiler)	P004, 5, 26, 27	A or E	Note 1
C12-N054 (CRD Hydraulic)	Local	D or E	Note 1
C72-N050 (Reactor Protection)	P004, 5, 26, 27	A or E	Note 1
E12-N055, 56 (RHR)	P018, 21	A or E	Note 1
E12-N060 (RHR)	P004, 18	A or E	Note 1
E21-N052, 53 (LPCS)	P001, 19	A or E	Note 1
E22-N050 (HPCS)	P024	A or E	Note 1
E22-N057 (HPCS)	P024	D or E	Note 1
E31-N083, 84, 85 (Leak Detection)	P017, 29	D or E	Note 1
E51-N051 (RCIC)	P017	D or E	Note 1
E51-N053 (RCIC)	P017	D or E	Note 1
E51-N055 (RCIC)	P017, 29	D or E	Note 1

Note 1

An inspection will be needed to determine which boards (A, D or E) have been installed. If A or D boards are installed, the correction is to install E boards.

