

U.S. NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT

Region I

Report No. 50-410/81-11

Docket No. 50-410

License No. CPPR-112 Priority - Category B

Licensee: Niagara Mohawk Power Corporation
300 Erie Boulevard West
Syracuse, New York

Facility Name: Nine Mile Point Unit 2

Inspection at: Syracuse, New York and Scriba, New York

Inspection conducted: September 29-30, 1981

Inspectors:	<u>W. H. Bannack for</u>	<u>10/15/81</u>
	R. A. Feil, Reactor Inspector	date signed
	<u>W. H. Bannack for</u>	<u>10/15/81</u>
	R. D. Schulz, Reactor Inspector	date signed
	(9/30 only)	
	<u>W. H. Bannack for</u>	<u>10/15/81</u>
	H. B. Kister, Chief Reactor	date signed
	Project Section 1C, Division of	
	Resident and Project Inspection	
Approved by:	<u>W. H. Bannack for</u>	<u>10/15/81</u>
	H. B. Kister, Chief Reactor	date signed
	Project Section 1C, Division of	
	Resident and Project Inspection	


Inspection Summary:

Inspection on September 29-30, 1981 (Report No. 50-410/81-11)

Areas Inspected: Routine, announced inspection by one regional based inspector, one section chief and one newly assigned resident inspector consisting of a discussion of corporate position regarding proposed QA reorganization and an orientation tour of the site. The inspection involved 20 inspector hours on-site.

Results: No items of noncompliance were identified.

8111050352 811019
PDR ADOCK 05000410
Q PDR



DETAILS

1. Persons Contacted

Niagara Mohawk Power Corporation (NMPC)

*	W. M. Bryant,	Q A Manager
*	J. L. Dillon,	Q A Engr., Site Lead
*	G. J. Doyle	Q A Technician
	S. F. Manno,	Project Manager, Unit 2
*	H. J. Mastin,	Lead Electrical Engineer, Site
	J. P. Ptak,	Assistant Manager of Construction, Site
	G. K. Rhode,	Vice President, SPM
	G. E. Sanford,	Manager of Construction, Site

Stone and Webster Engineering Corporation (SWEL)

	R. C. Balick,	Senior Q C Inspector
*	E. P. Eichen,	Ass't. Superintendent, Engineering
*	C. E. Hilton,	Superintendent of Construction
*	B. L. Holsinger,	Q A Engineer
	M. Nunes,	Ass't Q C Engineer
*	M. R. Oleson,	Ass't Superintendent, Engineering
*	G. W. Page,	Ass't to Superintendent, Engineering
*	H. T. Pierre,	Chief, Office Engineering
*	L. E. Shea,	Superintendent of Engineering
*	R. L. Wagner,	Project Manager

* denotes those present at exit meeting.

The inspectors conferred with other licensee and contractor personnel during the course of the inspection.

2. Proposed QA Function Reorganization

The inspectors met with the licensee's corporate staff to obtain clarification of the proposed reorganization of the Niagara Mohawk Power Corporation as it affects the QA organization for Nine Mile Point Unit 2. The proposed reorganization is described in OIE Inspection Report 50-410/81-08. In that report the inspector expressed concern that some functions, if directed and controlled by the Project Manager, may be contrary to Criterion 1, Appendix B, 10 CFR 50.

The licensee's corporate staff stated that the corporate position regarding the proposed reorganization is that which was presented to NRR at the January 26, 1981 meeting in Bethesda, Maryland. The licensee's corporate staff also stated that the definition of duties regarding the proposed QA reorganization have not yet been approved by Niagara Mohawk.



The inspectors acknowledged the comments of the licensee's corporate staff.

3. Facility Tour

The inspectors toured the site facilities, observed work in progress and contacted various licensee and contractor personnel in the process of the turnover inspection. Areas covered included the reactor building, primary containment, turbine building, administration building, water intake structure areas, the area of the ground fault and other service areas. The inspectors met with various licensee and contractor personnel to introduce the newly assigned resident inspector and to discuss office space requirements.

No items of noncompliance were identified.

4. Exit Interview

The inspectors met with the licensee's representatives (denoted in Paragraph 1) at the conclusion of the inspection on September 30, 1981. The inspectors summarized the purpose and scope of the inspection and the findings. The licensee acknowledged the inspector's findings.

