NIAGARA MOHAWK POWER CORPORATION/300 ERIE BOULEVARD WEST, SYRACUSE, N.Y. 13202/TELEPHONE (315) 474-1511

December 30, 1981

Office of Inspection and Enforcement Region I Attention: Mr. R.W. Starostecki, Director Division of Resident and Project Inspection U.S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406

> Nine Mile Point Unit 2 Docket No. 50-410

Dear Mr. Starostecki:

Your Inspection Report No. 50-410/81-10 identified a potential program weakness related to reporting of potential deficiencies in accordance with 10 CFR 50.55(e). In response, Niagara Mohawk's letter of November 30, 1981 indicated that we would advise you of the corrective action to be taken. As a result of Niagara Mohawk's Quality Assurance Department audit findings, all Stone and Webster Unit 2 Project engineering and support personnel who disposition and/or process Nonconformance and Disposition Reports (N&D's) both at the engineering headquarters (CHOC) and at the site, will receive additional detailed training. This additional training will address the specific requirements to document on the N&D's whether or not the nonconformance requires evaluation for reportability in accordance with 10 CFR 50.55(e).

Very truly yours,

NIAGARA MOHAWK POWER CORPORATION

RECICAL Richard C. Clancy
NO KUC Senior Vice President

RCC:bd

cc: Resident Inspector

.85 TVH 1 BH 1 28 REGION I NEMBC