

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9208240058 DOC. DATE: 92/08/13 NOTARIZED: NO DOCKET #
 FACIL: 50-410 Nine Mile Point Nuclear Station, Unit 2, Niagara Moha 05000410
 AUTH. NAME AUTHOR AFFILIATION
 MCCORMICK, M. J. Niagara Mohawk Power Corp.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards LER 91-017-01. Suppl issued to provide root causes
 for two missed TS requirements & results of root cause
 investigation for phase B main transformer failure on
 910813.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1423
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD1-1 LA	1 1	PD1-1 PD	1 1
MENNING, J	1 1		
INTERNAL: ACNW	2 2	ACRS	2 2
AEOD/DOA	1 1	AEOD/DSP/TPAB	1 1
AEOD/ROAB/DSP	2 2	NRR/DET/EMEB 7E	1 1
NRR/DLPQ/LHFB10	1 1	NRR/DLPQ/LPEB10	1 1
NRR/DOEA/OEAB	1 1	NRR/DREP/PRPB11	2 2
NRR/DST/SELB 8D	1 1	NRR/DST/SICB8H3	1 1
NRR/DST/SPLB8D1	1 1	NRR/DST/SRXB 8E	1 1
REG FILE 02	1 1	RES/DSIR/EIB	1 1
RGNI FILE 01	1 1		
EXTERNAL: EG&G BRYCE, J. H	2 2	L ST LOBBY WARD	1 1
NRC PDR	1 1	NSIC MURPHY, G. A	1 1
NSIC POORE, W.	1 1	NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK.
 ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 31 ENCL 31

A04



NINE MILE POINT—UNIT 2/P.O. BOX 63, LYCOMING, NY 13093

Martin J. McCormick Jr. PE
Plant Manager-Unit 2
Nuclear Generation

August 13, 1992
NMP87241

United States Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

RE: Docket No. 50-410
LER 91-17, Supplement 1

Gentlemen:

In accordance with 10CFR50.73, we hereby submit the following Licensee Event Report:

LER 91-17 Supplement 1 Is being submitted in accordance with the following: 1) 10CFR50.73 (a)(2)(iv), "Any event or condition that resulted in manual or automatic actuation of any Engineered Safety Feature (ESF) including the Reactor Protection System (RPS)"; and 2) 10CFR50.73 (a)(2)(i)(B), "Any operation or condition prohibited by the plant's Technical Specifications".

This supplement is being issued to provide the root causes for two missed Technical Specification requirements and to provide the results of the root cause investigation for the "B" Phase Main Transformer.

A 10CFR50.72 (a)(1)(i) report was made at 0612 hours on August 13, 1991.

Additionally, events were reported on a continuing basis as an open phone line was maintained between the plant and the U.S. Nuclear Regulatory Commission.

This report was completed in the format designated in NUREG 1022, Supplement 2, dated September 1985.

Very truly yours,

Martin J. McCormick Jr.
Plant Manager NMP2

MJM/RM/lmc

200082

ATTACHMENTS

xc: Thomas T. Martin, Regional Administrator Region I
Wayne L. Schmidt, Sr. Resident Inspector

9208240058 920813
PDR ADOCK 05000410
S PDR

Cent No
P708305084
IE22
11

