

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9610030139 DOC.DATE: 96/09/20 NOTARIZED: NO DOCKET #
 FACIL: 50-410 Nine Mile Point Nuclear Station, Unit.2, Niagara Moha 05000410
 AUTH.NAME AUTHOR AFFILIATION
 CONWAY, J.T. Niagara Mohawk Power Corp.
 RECIP.NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Informs NRC of change in corrective action re LER 96-003, Suppl 1, "Full Core Offload & Spent Fuel Pool Cooling Sys Operation Outside of Design Bases."

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD1-1.PD	1	HOOD, D	1
INTERNAL:	ACRS	1	AEOD/SPD/RAB	1
	AEOD/SPD/RRAB	1	<u>FILE CENTER</u>	1
	NRR/DE/ECGB	1	NRR/DE/EELB	1
	NRR/DE/EMEB	1	NRR/DRCH/HHFB	1
	NRR/DRCH/HICB	1	NRR/DRCH/HOLB	1
	NRR/DRCH/HQMB	1	NRR/DRPM/PECB	1
	NRR/DSSA/SPLB	1	NRR/DSSA/SRXB	1
	RES/DSIR/EIB	1	RGN1 FILE 01	1
EXTERNAL:	L ST LOBBY WARD	1	LITCO BRYCE, J H	1
	NOAC MURPHY, G.A	1	NOAC POORE, W.	1
	NRC PDR	1	NUDOCS FULL TXT	1

NOTE TO ALL "RIDS" RECIPIENTS:
 PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM OWFN 5D-5 (EXT. 415-2083) TO ELIMINATE YOUR NAME FROM
 DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 24 ENCL 0

C
A
T
E
G
O
R
Y

1
D
O
C
U
M
E
N
T



NIAGARA MOHAWK

GENERATION
BUSINESS GROUP

NINE MILE POINT NUCLEAR STATION/LAKE ROAD, P.O. BOX 63, LYCOMING, NEW YORK 13093

September 20, 1996
NMP2L 1663

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

RE: LER 96-03
Docket No. 50-410

Gentlemen:

On May 31, 1996, we submitted LER 96-03 Supplement 1, "Full Core Offload and Spent Fuel Pool Cooling System Operation Outside of Design Bases." Corrective Action number 3 in LER 96-03 Supplement 1 stated, "Divisional bus outage procedures, operating procedures, and RFO administrative procedures will be revised as appropriate to include SFC System design basis requirements. This will be completed prior to RFO5 in September 1996." This letter is to inform you of a change in that corrective action.

Since the fifth refueling outage (RFO5) workscope does not include divisional bus outages, the procedures governing these activities are not required for RFO5, and hence will not be revised prior to RFO5. Rather, these divisional bus outage procedures will be revised prior to their next use but no later than RFO6. In the interim, these procedures have been deactivated.

Very truly yours,

J. T. Conway
Plant Manager - Unit 2

JTC/TWR/kap

xc: Mr. H. J. Miller, Regional Administrator
Mr. B. S. Norris, Senior Resident Inspector

9610030139 960920
PDR ADOCK 05000410
S PDR