CATEGORY 3

REGULATOR INFORMATION DISTRIBUTION STEM (RIDS)

ACĆESSION NBR:9704150219 DOC.DATE: 97/04/03 NOTARIZED: NO DOCKET # FACIL:50-410 Nine Mile Point Nuclear Station, Unit 2, Niagara Moha 05000410 AUTH.NAME AUTHOR AFFILIATION

MCCORMICK, M.J. Niagara Mohawk Power Corp.

RECIP.NAME RECIPIENT AFFILIATION

Document Control Branch (Document Control Desk)

SUBJECT: Informs NRC that util corrected Unit 2 ISI program as

described in corrective action three of LER 96-012, Suppl 1.

DISTRIBUTION CODE: A047D COPIES RECEIVED:LTR LENCL CODE: SIZE: TITLE: OR Submittal: Inservice/Testing/Relief from ASME Code - GL-89-04

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL		RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	
ı	PD1-1 LA HOOD,D	1	1	PD1-1 PD	1	1
INTERNAL:	ACRS FILE CENTER 01 NUDOCS=ABSTRACT RES/DET/EIB	1 1 1		AEOD/SPD/RAB NRR/DE/EMEB OGC/HDS3 RES/DET/EMMEB	1 1 1	P P
EXTERNAL:	LITCO ANDERSON NRC PDR	1	1	NOAC	1	<i>ţ</i>

NOTE TO ALL "RIDS" RECIPIENTS: PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

9

A

Т

E

G

0

R

Y

1

D

0

IJ

M

E

N

T

30 • -. .



GENERATION BUSINESS GROUP

NINE MILE POINT NUCLEAR STATION/LAKE ROAD, P.O. BOX 63, LYCOMING, NEW YORK 13093/TELEPHONE (315) 349-2660 FAX (315) 349-2605

MARTIN J. McCORMICK JR. P.E. Vice President Nuclear Engineering April 3, 1997 NMP2L 1699

U.S. Nuclear Regulatory Commission Attention: Document Control Desk Washington, DC 20555

RE:

Nine Mile Point Unit 2 Docket No. 50-410 NPF-69

Subject:

Notification of Corrective Action Completion for ISI Program Plan

Gentlemen:

The purpose of this letter is to inform you that Niagara Mohawk has corrected the Nine Mile Point Unit 2 (NMP2) Inservice Inspection (ISI) program as described in corrective action three of Licensee Event Report (LER) 96-12, Supplement 1, submitted on January 17, 1997 (NMP2L 1683). Specifically, the corrective action required that the ISI Program Plan be corrected to indicate that 16 welds in the Reactor Water Cleanup (RWCU) System are considered Category D welds requiring augmented examination at least every other refueling outage.

Furthermore and as discussed in the LER, this notification corrects the error in a February 13, 1992 letter to the NRC (NMP2L 1339), in which Niagara Mohawk had incorrectly indicated that the 16 shop fabricated RWCU system welds had been reclassified as Category D in accordance with Generic Letter 88-01.

Should you have any questions regarding this matter, please contact Mr. R. Dean, the Unit 2 Engineering Manager, at 315-349-4240.

Very truly yours,

M. J. McCormick

Vice President, Nuclear Engineering

MJM/AFZ/lmc

xc:

Mr. H. J. Miller, Regional Administrator Region I

Mr. S. S. Bajwa, Acting Director, Project Directorate I-1, NRR

Mr. B. S. Norris, Senior Resident Inspector

Mr. D. S. Hood, Senior Project Manager, NRR

Records Management

9704150219 970403 PDR* ADDCK 05000410 Q

A047/0

.

.