

THE CHURCH OF
JESUS CHRIST
OF LATTER-DAY SAINTS

FACILITIES MANAGEMENT

Ontario OR. FM Group
3958 Hwy. 201
Ontario OR. 97914
Office (541) 889-2594
Fax (541) 881-1555

02/24/2017

Director of FSME

Attn: GLTS

USNRC

Washington, DC 20555-0001

In fulfillment of the requirements of 10 CFR 31.5 (c) 8, we hereby notify you that on 02/24/2017 we transferred the self-luminous exit signs listed on the attached spreadsheet to SRBT, 320 Boundary Rd., Suite 140, Pembroke, Ontario, K8A 6W5, Canada with CNSC License #NSPFOL-13.00/2015.

As required, for each sign listed on the spreadsheet, we include the name of the manufacturer, model number, and serial number.

If you should have any questions, please contact: Frazer Peterson.

Frazer Peterson 541-889-2594

Sincerely,



Frazer Peterson

Encl.

Box 1

SERIAL NUMBER SPREADSHEET

Company Name	Ontario OR FMG	Date	1/27/17
Address 1	3958 HWY 201	Isolite RMA #	
Address 2		EWS Order #	1375
Address 3		MTS Order #s	156903
City/State	Ontario, OR	Contact Name	Frazer Peterson
Zip/Post Code	97914	Contact Phone	541-889-2594
Country	USA	Contact FAX	541-881-1555
		Contact E-mail	PetersonFC@LDSchurch.org

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "CI" or "TBq"
				Month	Year	
1	Shield	201	E4093	06	91	10-CI
2	Shield	201	E4097	06	91	10-CI
3	Shield	201	E4092	06	91	10-CI
4	Shield	201	E4091	06	91	10-CI
5	Shield	201	E4090	06	91	10-CI
6	Shield	201	E4089	06	91	10-CI
7	Shield	201	E4088	06	91	10-CI
8	Shield	201	E3270	05	91	10-CI
9						
10						
11						
12						
13						
14						
15						

*The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

Box #2

SERIAL NUMBER SPREADSHEET

Company Name	Ontario DR FMG	Date	1/27/17
Address 1	3958 HWY 201	Isolite RMA #	
Address 2		EWS Order #	1375
Address 3		MTS Order #s	156903
City/State	Ontario OR	Contact Name	Frazer Peterson
Zip/Post Code	97914	Contact Phone	541-889-2594
Country	USA	Contact FAX	541-881-1555
		Contact E-mail	PetersonFC@LDSchurch.org

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "CI" or "TBq"
				Month	Year	
1	Shield	201	E4094	6	91	10 - CI
2	Shield	201	E3269	5	91	10 - CI
3	Shield	201	E3271	5	91	10 - CI
4	Shield	201	E3272	5	91	10 - CI
5	Shield	201	E4081	6	91	10 - CI
6	Shield	201	E4082	6	91	10 - CI
7	Shield	201	E4084	6	91	10 - CI
(16) 8	Shield	201	E4085	6	91	10 - CI
9						
10						
11						
12						
13						
14						
15						

*The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

SERIAL NUMBER SPREADSHEET

Company Name	Ontario DR FMG	Date	11/27/17
Address 1	3958 HWY 201	Isolite RMA #	
Address 2		EWS Order #	1375
Address 3		MTS Order #s	156903
City/State	Ontario, OR	Contact Name	Frazer Peterson
Zip/Post Code	97914	Contact Phone	541-889-2594
Country	USA	Contact FAX	541-881-1555
		Contact E-mail	Peterson.FC@LDSchurch.org

24

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "CI" or "TBq"
				Month	Year	
1	Shield	201	E 4086	6	91	10-CI
2	Shield	201	E 4087	6	91	10-CI
3	Shield	201	D 3647	6	90	12-CI
4	Shield	201	E 3983	6	91	10-CI
5	Shield	201	E 3984	6	91	10-CI
6	Shield	201	E 3985	6	91	10-CI
7	Shield	201	E 3986	6	91	10-CI
8	Shield	201	E 3435	6	91	10-CI
9						
10						
11						
12						
13						
14						
15						

**The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.*

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

Box #4

SERIAL NUMBER SPREADSHEET

Company Name	Ontario DR Fmg	Date	1/27/17
Address 1	3958 Hwy 201	Isolite RMA #	
Address 2		EWS Order #	1375
Address 3		MTS Order #s	156903
City/State	Ontario, OR	Contact Name	Frazer Peterson
Zip/Post Code	97914	Contact Phone	541-889-2594
Country	USA	Contact FAX	541-881-1555
		Contact E-mail	PetersonFC@LDSchurch.org

(32)

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "CI" or "TBq"
				Month	Year	
1	Shield	201	E 3436	6	91	10-CI
2	Shield	201	E 3437	6	91	10-CI
3	Shield	201	E 3438	6	91	10-CI
4	Shield	201	E 3439	6	91	10-CI
5	Shield	201	E 3440	6	91	10-CI
6	Shield	201	E 3441	6	91	10-CI
7	Shield	201	E 3442	6	91	10-CI
8	Shield	201	E 3443	6	91	10-CI
9						
10						
11						
12						
13						
14						
15						

**The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.*

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

Box #5

SERIAL NUMBER SPREADSHEET

Company Name	Ontario OR FINE	Date	1/27/17
Address 1	3958 HWY 201	Isolite RMA #	
Address 2		EWS Order #	1375
Address 3		MTS Order #s	156903
City/State	Ontario, OR	Contact Name	Frazer Peterson
Zip/Post Code	97914	Contact Phone	541-889-2594
Country	USA	Contact FAX	541-881-1555
		Contact E-mail	PetersonFC@LDSchurch.org

140

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "CI" or "TBq"
				Month	Year	
1	Shield	201	E 3444	6	91	10-CI
2	Shield	201	E 3445	6	91	10-CI
3	Shield	201	E 3447	6	91	10-CI
4	Shield	201	E 3448	6	91	10-CI
5	Shield	201	E 3449	6	91	10-CI
6	Shield	201	E 3450	6	91	10-CI
7	Shield	201	E 3451	6	91	10-CI
8	Shield	201	E 3452	6	91	10-CI
9						
10						
11						
12						
13						
14						
15						

*The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.

Box 8

SERIAL NUMBER SPREADSHEET

Company Name	Ontario OR FMG	Date	11/27/17
Address 1	3958 HWY 201	Isolite RMA #	
Address 2		EWS Order #	1375
Address 3		MTS Order #s	156903
City/State	Ontario, OR	Contact Name	Frazer Peterson
Zip/Post Code	97914	Contact Phone	541-889-2594
Country	USA	Contact FAX	541-881-1555
		Contact E-mail	PetersonAFC@ldschurch.org

42

	Manufacturer Name	Model No.	Serial No.	Manufacture Date		Activity Include "Ci" or "TBq"
				Month	Year	
1	SHIELD	201	E 3453	6	91	10-C1
2	SHIELD	B 100	650207	11	99	20-C1
3						
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						

*The above information should be on the signs labels. If any information on the sign is missing please fill in the fields with "missing" or "illegible", etc. Please print clearly. A double sign is counted as "TWO" signs—not "ONE" Please make note of this.

Once we have received and processed this information an RMA number will be issued.

If you have more signs that this form holds, please copy additional pages and filling all necessary information.