



KHNP

KOREA HYDRO & NUCLEAR POWER CO., LTD

70-1312-gil, Yuseong-daero, Yuseong-gu, Daejeon, 305-343, KOREA

Tel: +82-42-870-5400 / Fax: +82-42-870-5449

<http://www.khnp.co.kr>

March 23, 2017
Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Attention: Mr. Jeff Ciocco
Division of New Reactor Licensing

Docket No. 52-046
MKD/NW-17-0079L

Subject: Revised Response to RAI 198-8208 for Question 14.02-23 (Rev. 2)

References: 1) NRC Request for Additional Information 198-8208, dated September 4, 2015
2) KHNP Letter MKD/NW-15-0313L, Response to RAI 198-8208, dated December 9, 2015
3) KHNP Letter MKD/NW-16-0696L, Revised Response to RAI 198-8208 for Question 14.02-23, dated June 30, 2016

KHNP is hereby submitting a revised response to RAI 198-8208, dated September 4, 2015. The revised response addresses Question 14.02-23 and provides additional information on the detection of mis-positioned in-core detectors through testing.

The enclosure contains the revised response to RAI 198-8208 for Question 14.02-23 (Rev. 2) (Non-Proprietary).

If additional information or clarification is required, please contact Daegeun Ahn, Director of KHNP Washington DC Center at ahn.daegeun@khnp.co.kr or 703-388-0592.

Sincerely,

Han-gon Kim
Project Manager
Advanced Reactors Development Laboratory
Korea Hydro & Nuclear Power Co., Ltd.

Enclosure: Revised Response to RAI 198-8208 for Question 14.02-23 (Rev. 2) (Non-Proprietary)

Enclosure

Revised Response to RAI 198-8208 for Question 14.02-23 (Rev. 2)

(Non-Proprietary)

March 23, 2017