




Commonwealth Edison
 One First National Plaza, Chicago, Illinois
 Address Reply to: Post Office Box 767
 Chicago, Illinois 60690

BBS Ltr.#579-74

Dresden Nuclear Power Station
 R. R. #1
 Morris, Illinois 60450
 August 12, 1974



Mr. James G. Keppler, Regional Director
 Directorate of Regulatory Operations-Region III
 U. S. Atomic Energy Commission
 799 Roosevelt Road
 Glen Ellyn, Illinois 60137

50-237


SUBJECT: LICENSE DPR-19, DRESDEN NUCLEAR POWER STATION, UNIT #2, REPORT ON INSPECTION OF BERGEN PATERSON SHOCK SUPPRESSORS AND RESTRAINTS.

Dear Mr. Keppler:

This is a courtesy letter to report information concerning the stations sixth inspection of Bergen Paterson shock suppressors on Unit 2 on July 28, 1974. All 31 snubbers were found to be operable. Three had low oil level and the "as found" and "as left" readings are shown for these.

<u>Snubber No.</u>	<u>Piston Position</u>	<u>Indicator Reading</u>	<u>Seal Material</u>
1	3½	2	E-P
2	3	6½	PU
2 after filling	3	3½	PU
3	4	4	PU
4	3½	2	PU
5	3½	2½	PU
6	3½	2	PU
7	2½	3	PU
8	3	3	PU
9	4	2 No scale	E-P
10	3	3	E-P
11	3	2	PU
12	3½	3½	E-P
13	3	3½	E-P/PU
14	5½	3	PU
15	4	1	PU
16	3½	4	PU
17	4½	3	PU
18	2	1½	E-P
19	2	1	E-P
20	2½	2	E-P
21	4½	5	PU
22	2	2	E-P
23	4	4	E-P
24	4	4½	PU

REGULATORY DOCKET FILE COPY




August 12, 1974

<u>Snubber No.</u>	<u>Piston Position</u>	<u>Indicator Reading</u>	<u>Seal Material</u>
25	4½	5	E-P
26	3	5½	E-P
26 after filling	3	3½	E-P
27	3½	4	E-P
28	2½	6½	E-P
28 after filling	2½	2	E-P
29	3½	3½	E-P
30	3	1	E-P
31	3	2-3/4	E-P

E-P - Ethylene Propylene Seal Material
PU - Polyurethane Seal Material

Sincerely,



B. B. Stephenson
Superintendent

BBS:LJD:do