




Commonwealth Edison
 One First National Plaza, Chicago, Illinois
 Address Reply to: Post Office Box 767
 Chicago, Illinois 60690

August 9, 1974



Mr. Angelo Giambusso
 Deputy Director for Reactor Projects
 Directorate of Licensing
 Office of Regulation
 U. S. Atomic Energy Commission
 Washington, D. C. 20545

Subject: Review of Dresden Units 2 and 3, and Quad-Cities
 Units 1 and 2, Control Circuit Deficiencies,
 AEC Dkts 50-237, 50-249, 50-254 and 50-265



Dear Mr. Giambusso:

In a letter to you dated April 25, 1974 concerning this subject, the schedule for completing the associated corrective measures was indicated as the 1974 refueling outages. The corrective measures were completed on Quad-Cities Unit 1 during its recently completed refueling outage. However, because delivery of the necessary materials was delayed, the corrective measures were not completed during the Dresden Unit 3 refueling outage. All materials have been delivered and the corrective measures for Unit 3 will be completed during the next outage of at least five (5) days. The refueling outages for Dresden Unit 2 and Quad-Cities Unit 2 are to begin December 1st and January 1st, respectively, at which time the necessary modifications are to be made.

It is not expected that any further change in these schedules will be necessary; however, you will be notified if changes do occur. Administrative Controls that were discussed in a letter to Mr. D. J. Skovholt dated March 7, 1973 will be maintained until the final corrective measures are completed.

Very truly yours,

Byron Lee Jr.
 Byron Lee, Jr.
 Vice-President

REGULATORY DOCKET FILE COPY

8396

2076