

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Conformatech, Inc.
1425 East Apache Park Place
Tucson, AZ

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission
Region IV, 1600 East Lamar Blvd
Arlington, Texas 76011-4511

REPORT NO: 2017-001

3. DOCKET NUMBER

030-37125

4. LICENSE NUMBER

02-29222-01

5. DATE OF INSPECTION

March 14, 2017

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.
- Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

Title 10 CFR 71.5(a) states, each licensee who transports licensed material outside the site of usage as specified in the NRC license or where transport is on public highways or who delivers licensed material to a carrier for transport, shall comply with the applicable requirements of the Department of Transportation regulations in 49 CFR Parts 107, 171-180, and 390-397, appropriate to the mode of transport.




49 CFR 172.704(e)(2) requires a hazmat employee to receive the training required by 49 CFR 172 at least once every three years.

Contrary to the above, from March 24, 2014 to May 12, 2015, the licensee failed to provide the training required by 49 CFR 172, Subpart H at least once every three years. Specifically from March 24, 2014 to April 23, 2014 and from December 2, 2014 to May 12, 2015, licensee employees transported portable gauges in NRC jurisdiction and the employees has last received the required training between December 6, 2001 and December 30, 2010.

Corrective Action: The licensee had the authorized gauge users complete hazmat refresher training on April 6, 2017. Copies of the certificates were provided to the inspector via email on April 11, 2017.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Gerry Tarab		4-18-17
NRC INSPECTOR	Marti Poston		4-17-17
BRANCH CHIEF	Vivian H. Campbell		4/28/2017

- Non-Public
- Sensitive - Security-Related
- Public
- Non-Sensitive