



Commonwealth Edison
One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

REGULATORY DOCKET FILE COPY

November 17, 1977



Mr. Karl R. Goller, Assistant Director
Division of Operating Reactors
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Subject: Dresden Station Units 2 and 3
High Energy Line Break Analysis
NRC Docket Nos. 50-237 and 50-249

Reference (a): Dresden Station Special Report
No. 37, Revision 1.

Dear Mr. Goller:

Attached is Appendix E to Special Report No. 37 for Dresden Station Units 2 and 3. This Appendix consists of an analysis of the effects of postulated pipe breaks outside the containment on electrical conduits and cable trays.

The current plant modification schedule is as follows:

Dresden Unit 2	Fall 1977 Refuel Outage
Dresden Unit 3	March 1, 1978

One (1) signed original and 39 copies of this report are provided for your review.

Very truly yours,

M. S. Turbak

M. S. Turbak
Nuclear Licensing Administrator
Boiling Water Reactors

Attachment

773490085