

Baker

August 3, 1995

US Nuclear Regulatory Commission, Region I
475 Allendale Road
King of Prussia, PA 19406-1415

Attention: Kathleen Dolce
Nuclear Materials Safety Branch
Division of Radiation
Safety and Safeguards

Subject: License Number 37-28518-01
Docket No. 030-31690
Control No. 121859
NRC letter received July 24, 1995

Michael Baker Jr., Inc.
Construction Management Services
P.O. Box 60277
Harrisburg, Pennsylvania 17106-0277

Office Location:
3600 Vartan Way, Second Floor
Harrisburg, Pennsylvania 17110

(717) 541-5262
FAX (717) 541-5238

MS16
P-3

Dear Ms. Dolce:

This will advise that Policy and Guidance Directive PG 2-07, "Standard Review Plan for Applications for the Use of Sealed Sources in Portable Gauging Devices," dated September 1994, provided by NRC was followed in preparing the license application. A review of the Draft Regulatory Guide DG-0008 entitled "Applications for the use of Sealed Sources in Portable Gauging Devices," dated May 1995, provided with the subject letter discloses some differences in application commitment language and format. The following are provided in response to the additional information requested to enable continuation of our license application:

1. A commitment is made that the NRC will be notified in accordance with 10CFR 30.50(b)(2) if a sealed source becomes lodged in a hole and it becomes apparent that recovery efforts will be unsuccessful.
2. Annual Audit of the Radiation Safety program will be made as described in Appendix I of Policy and Guidance Directive PG 2-07 (Rev. 0) dated September 1994 as stated in the license application. (1) The audits will be conducted by Gary R. Chodkowski, RSO (2) The scope and extent of the audits will be that outlined in Appendix I as referenced above, (3) A commitment is made to conduct the audits at intervals not to exceed 12 months and records of the audits will be maintained for at least three years after the record is made, (4) Management commits to review the documented results of the audit promptly after the audits completion, and (5) A commitment is made to take prompt action to correct deficiencies identified during audits, to inform all personnel (including those at other locations and those working under other licenses) of the deficiencies and the actions management expects its personnel to take to avoid similar deficiencies.
3. The radiation detection equipment will be calibrated annually.

OFFICIAL RECORD COPY



A Total Quality Corporation

ML 10

121859


AUG -7 1995

Ms. Kathleen Dolce
August 3, 1995
Page 2

We trust the above responses are satisfactory and will enable license application processing to be completed and issued. Please contact me at (717) 671-2342 with any questions in regard to the above.

Sincerely yours,

MICHAEL BAKER JR., INC.

A handwritten signature in black ink, appearing to read "Larry K. McKinney". The signature is written in a cursive style with a long, sweeping tail that extends downwards and to the right.

Larry K. McKinney, P.E.
Radiation Safety Officer

LKM:tlg

cc: GJKurgan
TJZagorski
GRChodkowski