



RECEIVED
MAY 3 8 2017

DNMS

May 3, 2017

Mr. Mark R. Shaffer, Director
Division of Nuclear Materials Safety
1600 E. Lamar Blvd.
Arlington, TX. 76011-4511

SUBJECT: NRC INSPECTION REPORT 030-38990/2017-001

Dear Mr. Shaffer:

In response to US NRC Letter dated April 24, 2017, we accept the Inspection Findings with the corresponding corrective actions characterized as follows:

- Failure to receive and possess byproduct material except as authorized in a specific or general license issued in accordance with the regulations in Title 10 of Code of Federal Regulations, Chapter 1. Our corrective action was taken in the form of obtaining License number 56-35371-01, allowing storage of the material at 133 Route 3, Dededo, Guam.
- Conduct program in accordance with NRC byproduct materials license. Our corrective action was taken in the form of obtaining an amendment to License number 56-35371-01, in accordance with a letter dated January 11, 2017, naming John Y. Young, M.D. as the Radiation Safety Officer.

Because GRMC does not intend on using the strontium-90 sources to calibrate our linear accelerator dosimetry equipment, we continue to take steps to properly transfer, export, or dispose of the sources.

Should you have any questions, please contact me at 671-727-0303.

Sincerely,

Alan Funtanilla, Chief Administrative Officer
Guam Regional Medical City
133 Route 3
Dededo, Guam 96912