

APPENDIX A

NOTICE OF VIOLATION

Pennsylvania Power and Light Company

Docket No. 50-387

This refers to the inspection conducted by a representative of the Region I (Philadelphia) office at the Susquehanna Steam Electric Station Unit 1, Berwick, Pennsylvania, of activities authorized by NRC License No. CPPR-101.

During this inspection, conducted on March 6-8, 1979, the following apparent item of noncompliance was identified:

10 CFR 50, Appendix B, Criterion V, states, in part, that: "Activities affecting quality shall be prescribed by documented instructions, procedures, or drawings ... and shall be accomplished in accordance with these instructions, procedures, or drawings."

The Susquehanna PSAR, Appendix D, Quality Assurance Program, Paragraph D.2.5 states, in part, that: "Activities affecting quality will be prescribed by documented instructions, procedures, or drawing appropriate to the circumstances ..." Bechtel Field Project Procedure E-8, Revision 0, states in Section 6.3.1 that, "Aluminum conductors shall be thoroughly brushed with a fine bristle stainless steel wire brush immediately prior to installation of the conductor to remove any oxide film from the conductor strands."

Contrary to the above, on March 7, 1979, the installation of terminations on two 500 MCM aluminum conductors for the 250 VDC battery charger ID653B was completed without brushing with a wire brush as required.

This item is an infraction.

7907280585