



TWO NORTH NINTH STREET, ALLENTOWN, PA. 18101

PHONE: (215) 821-5151

NORMAN W. CURTIS
Vice President-Engineering & Construction
821-5381

April 30, 1980

Mr. Boyce H. Grier
Director, Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

SUSQUEHANNA STEAM ELECTRIC STATION
STATUS UPDATE OF DEFICIENCIES INVOLVING PGCC
CABLE CONNECTORS (MCAR 1-29)
ER 100450 FILE 840-4
PLA-477

References: PLA-437 dated 01/08/80
PLA-313 dated 01/15/79
PLA-301 dated 11/14/78

Dear Mr. Grier:

This letter serves as a supplement to our earlier correspondence on the above listed subject. Since PP&L and Bechtel Engineering are still in the process of evaluating the cause and corrective actions necessary to resolve the defective conditions, our final report on the deficiencies involving damage to cable connectors will be temporarily delayed.

We anticipate providing a final report on the subject deficiencies in July, 1980.

Very truly yours,

N. W. Curtis
Vice President-Engineering & Construction

ARS:mcb

cc: Mr. Victor Stello (15)
Director-Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. G. McDonald, Director
Office of Management Information & Program Control
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8006120106 S

PENNSYLVANIA POWER & LIGHT COMPANY

Mr. Boyce H. Grier

- 2 -

April 30, 1980

cc: Mr. Robert M. Gallo
U. S. Nuclear Regulatory Commission
P. O. Box 52
Shickshinny, Pennsylvania 18655