

PP&L

TWO NORTH NINTH STREET, ALLENTOWN, PA. 18101 PHONE: (215) 821-5151

NORMAN W. CURTIS
Vice President-Engineering & Construction-Nuclear
821-5381

November 3, 1980

Mr. Boyce H. Grier, Director
Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION
IE BULLETIN 80-20
ER 100450 FILE 840-4
PLA-566

US NRC
DISTRIBUTION SERVICES
BRANCH

1980 NOV 14 AM 8 44

DISTRIBUTION
SERVICES UNIT

DOCKET NOS. 50-387
AND 50-388

Dear Mr. Grier:

The following information completes our response to IE Bulletin 80-20, "Failures of Westinghouse Type W-2 Spring Return to Neutral Control Switches". This information supplements our previous response, PLA-543, dated September 23, 1980.

To ensure that the normally closed neutral position contacts described in the bulletin are not used in the future, a note will be added to applicable drawings warning against their use and referencing IE Bulletin 80-20.

Total estimated manpower expended on IE Bulletin 80-20:

- a) Report preparation and review 100 manhours
- b) Corrective actions 1000 manhours
1100 manhours

Very truly yours,

NW Curtis
N. W. Curtis

RMH/mks

cc: Director
Division of Reactor Operations Inspection
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. R. M. Gallo
U.S. Nuclear Regulatory Commission
P.O. Box 52
Shickshinny, PA 18655

