



TWO NORTH NINTH STREET, ALLENTOWN, PA. 18101    PHONE: (215) 770-5151

NORMAN W. CURTIS  
Vice President-Engineering & Construction-Nuclear  
770-5381

March 2, 1981

Mr. Boyce H. Grier  
Director, Region I  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

SUSQUEHANNA STEAM ELECTRIC STATION  
STATUS UPDATE OF A DEFICIENCY RELATING  
TO SHIMMING OF BASE PLATES  
ERS 100450/100508    FILE 840-4/900-10  
PLA-646

Reference: PLA-586 dated 12/9/80

Dear Mr. Grier:

This letter serves to supplement the above reference correspondence which advised the Commission of a deficiency relating to the use of pipe shims around equipment anchors.

Based on the fact that a thorough investigation of this deficiency is still in progress, PP&L will not be able to meet the February submittal date as projected in our PLA-586. Consequently, we have assessed progress to date and expect to provide a final report in April 1981.

Very truly yours,

N. W. Curtis  
Vice President-Engineering & Construction-Nuclear

FLW:sab

8104270029

Mr. Boyce H. Grier

- 2 -

March 2, 1981

cc: Mr. Victor Stello (15)  
Director-Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. G. McDonald, Director (1)  
Office of Management Information & Program Control  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Mr. Robert M. Gallo  
U. S. Nuclear Regulatory Commission  
P.O. Box 52  
Shickshinny, PA 18655

