

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

AIA 52

ACCESSION NBR: 8301140003 DOC. DATE: 83/01/11 NOTARIZED: NO DOCKET #
 FACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylvania 05000387
 AUTH. NAME AUTHOR AFFILIATION
 CURTIS, N.W. Pennsylvania Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 SCHWENCER, A. Licensing Branch 2

SUBJECT: Submits addl info in support of proposed Amend 11 to License NPF-14. Fire Zones corresponding to installed sprinkler sys misinterpreted due to error in Tech Specs. Zones reinterpreted.

DISTRIBUTION CODE: B002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: Licensing Submittal: Fire Protection

NOTES:

	RECIPIENT ID CODE/NAME		COPIES			RECIPIENT ID CODE/NAME		COPIES	
	NRR	LB2 BC	LTTR	ENCL		PERCH, R.	01	LTTR	ENCL
INTERNAL:	ELD/HDS4		1	0	IE FILE	07	1	1	
	NRR/DE/CEB	06	2	2	NRR/DSI/ASB		1	1	
	<u>REG FILE</u>	04	1	1	RGN1		1	1	
EXTERNAL:	ACRS	10	6	6	LPDR	03	2	2	
	NRC PDR	02	1	1	NSIC	05	1	1	
	NTIS		1	1					



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

Norman W. Curtis
Vice President-Engineering & Construction-Nuclear
215 / 770-5381

JAN 11 1983

Mr. A. Schwencer, Chief
Licensing Branch No. 2
U. S. Nuclear Regulatory Commission
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION
ADDITIONAL INFORMATION IN SUPPORT OF
PROPOSED AMENDMENT 11 TO LICENSE NO. NPF-14
ER 100450 FILE 841-8
PLA-1453

Docket No. 50-387

Dear Mr. Schwencer:

The purpose of this letter is to provide additional information in support of proposed Amendment 11 to License No. NPF-14. The error in the Technical Specification with respect to sprinkler systems in Fire Zones 1-2B and 1-6A is the result of a misinterpretation of the Fire Zone corresponding to the installed sprinkler systems.

A preaction sprinkler system was installed in Fire Zone 1-2B and has been properly tested and maintained operable since initial fuel load. This sprinkler system protects essential equipment and should be included in the Technical Specifications.

No sprinkler systems are installed in Fire Zone 1-6A, contrary to what is shown in the Fire Protection Review Report, Revision 1, and the Technical Specifications. However, this zone was reanalyzed and subsequently subdivided into two fire zones; 1-6A and 1-6I. An analysis of the two zones, consistent with the analyses presented in the Fire Protection Report, indicates that there is no redundant essential safe shutdown equipment in either of these zones for single unit operation and therefore, automatic sprinkler protection is not required. In accordance with other commitments, two photoelectric smoke detectors are being installed in Fire Zone 1-6I.

In accordance with Technical Specifications a continuous fire watch has been established in fire zone 1-6A (as originally depicted in the FPRR, Revision 1) and will continue until the Technical Specification is changed. In addition, following the Technical Specification change, Fire Zone 1-6I will be included in hourly fire watch rounds until the smoke detectors are installed, tested and declared operable.

8301140003 830111
PDR ADOCK 05000387
F PDR

13007

The first part of the document discusses the importance of maintaining accurate records of all transactions. It emphasizes that every entry should be supported by a valid receipt or invoice. This ensures transparency and allows for easy verification of the data.

Furthermore, it is noted that the records should be kept in a secure and accessible location. Regular audits are recommended to identify any discrepancies or errors early on. This proactive approach helps in maintaining the integrity of the financial information.

In addition, the document highlights the need for clear communication between all parties involved. Regular meetings and reports should be conducted to keep everyone informed of the current status and any upcoming changes. This fosters a collaborative environment where everyone is working towards the same goals.

Finally, it is stressed that the information should be kept up-to-date. Any new transactions or changes in the data should be recorded immediately. This ensures that the records always reflect the most current and accurate information available.

The second part of the document provides a detailed overview of the current financial performance. It includes a summary of the revenue generated, the expenses incurred, and the resulting profit or loss for the period. This analysis is crucial for understanding the overall health of the organization.

Key areas of focus are identified, such as the high-performing departments and the areas that require further attention. Specific strategies are proposed to address the challenges and capitalize on the opportunities. This strategic planning is essential for long-term success.

The document concludes with a series of recommendations and action items. These are designed to guide the organization in implementing the proposed strategies and improving its financial management practices. It is a call to action for all stakeholders to work together and ensure the success of the organization.

Overall, the document serves as a comprehensive guide for managing financial records and improving organizational performance. It provides a clear framework for action and a path forward for the organization.

JAN 11 1983

Page 2

The Fire Protection Review Report is being updated to correct any deficiencies and to include the new analysis of Fire Zones 1-6A and 1-6I. Revision 2 has been submitted December 31, 1982.

Very truly yours,



N. W. Curtis

Vice President-Engineering and Construction-Nuclear

cc: R. L. Perch- NRC

MEMORANDUM FOR THE DIRECTOR, FBI

RE: [Illegible]

[Illegible]