

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8505230081 DOC. DATE: 85/05/20 NOTARIZED: NO DOCKET #
 FACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylvania 05000387
 AUTH. NAME AUTHOR AFFILIATION
 CURTIS, N.W. Pennsylvania Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 BUTLER, W.R. Licensing Branch 2

SUBJECT: Informs that design mods on scram discharge vol sys, including redundant vent & drain valves & diverse & redundant scram discharge vol instrumentation for each instrumented vol, implemented.

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: OR Submittal: General Distribution

NOTES: 1cy NMSS/FCAF/PM. LPDR 2cys Transcripts. 05000387
 OL: 07/17/82

	RECIPIENT ID CODE/NAME		COPIES LTTR ENCL		RECIPIENT ID CODE/NAME		COPIES LTTR ENCL
	NRR L82 BC	01	7				
INTERNAL:	ACRS	09	6		ADM/LFMB		1
	ELD/HDS4		1		NRR/DE/MTEB		1
	NRR/DL DIR		1		NRR/DL/ORAB		1
	NRR/DL/TSRG		1		NRR/DSI/METB		1
	NRR/DSI/RAB		1		<u>REG FILE</u>	04	1
	RGN1		1				
EXTERNAL:	EG&G BRUSKE, S		1		LPDR	03	2
	NRC PDR	02	1		NSIC	05	1
NOTES:			3				

TOTAL NUMBER OF COPIES REQUIRED: LTTR 31 ENCL 20

1944

1. The first part of the report deals with the general situation in the country. It is noted that the economy is in a state of depression and that the government is facing a serious financial crisis. The report also mentions that the population is suffering from a lack of food and clothing.

2. The second part of the report discusses the political situation. It is noted that the government is weak and that there is a lack of unity among the different political groups. The report also mentions that the military is in a state of disarray and that there is a risk of a coup d'état.

3. The third part of the report deals with the social situation. It is noted that there is a high level of unemployment and that the living standards are very low. The report also mentions that there is a widespread feeling of hopelessness and despair among the population.

4. The fourth part of the report discusses the international situation. It is noted that the country is in a state of isolation and that it is being treated as a pariah state by the major powers. The report also mentions that there is a risk of the country being partitioned.

5. The fifth part of the report deals with the future of the country. It is noted that the country needs a strong and stable government and that it needs to be able to attract foreign investment. The report also mentions that the country needs to be able to provide for the basic needs of its population.



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

Norman W. Curtis
Vice President-Engineering & Construction-Nuclear
215/770-7501

MAY 20 1985

Director of Nuclear Reactor Regulation
Attention: Mr. W. R. Butler, Chief
Licensing Branch No. 2
Division of Licensing
U.S. Nuclear Regulatory Commission
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSE CONDITION 2.C.(17)(b) TO FACILITY
OPERATING LICENSE NO. NPF-14
ER 100450 FILE 841-2
PLA-2470

Docket No. 50-387

Dear Mr. Butler:

This letter is to inform you that in accordance with License Condition 2.C.(17)(b) to Facility Operating License No. NPF-14, Pennsylvania Power & Light Company has implemented design modifications on the scram discharge volume system that include the following:


- (1) Redundant vent and drain valves, and
- (2) Diverse and redundant SDV instrumentation for each instrumented volume, including both delta pressure sensors and float sensors.

The completion of these modifications closes this license condition. If you have any questions, please contact us.

Very truly yours,

N. W. Curtis
Vice President-Engineering & Construction-Nuclear

cc: M. J. Campagnone USNRC
R. H. Jacobs USNRC



*Adol
1/0*



[The text in this section is extremely faint and illegible due to low contrast and scan quality. It appears to be several paragraphs of a document.]