

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8911160023 DOC. DATE: 89/11/06 NOTARIZED: YES DOCKET #
 FACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylv 05000387
 50-388 Susquehanna Steam Electric Station, Unit 2, Pennsylv 05000388
 AUTH. NAME AUTHOR AFFILIATION
 KEISER, H.W. Pennsylvania Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 BUTLER, W.R. Project Directorate I-2

SUBJECT: Revised response to NRC Bulletin 88-010.

DISTRIBUTION CODE: IE21D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: Bulletin Response 88-10 - Nonconforming Molded Case Circuit Breakers.

NOTES: LPDR 1 cy Transcripts. 05000387
 LPDR 1 cy Transcripts. 05000388

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID	CODE/NAME	LTTR	ENCL		ID	CODE/NAME	LTTR	ENCL
	PD1-2	LA	1	0		PD1-2	PD	1	1
		THADANI, M	1	1					
INTERNAL:	AEOD/DOA		1	1	AEOD/DSP/TPAB			1	1
	NRR DOEA/GCB	11	1	1	NRR GILL, A.S.			1	1
	NRR GUILLEN, J		1	1	NRR POTAPOUS, U			1	1
	NRR STONE, J.C.		1	1	NRR/DEST/ADS 7E			1	1
	NRR/DEST/MEB	9H	1	1	NRR/DOEA/EAB	11		1	1
	NRR/DOEA/GCB	11	1	1	NRR/DREP/EPB	10		1	1
	NRR/PMAS/ILRB	12	1	1	NUDOCS-ABSTRACT			1	1
	REG FILE	02	1	1	RES/DSIR/EIB			1	1
	RGNI	FILE 01	1	1					
EXTERNAL:	LPDR		1	1	NRC PDR			1	1
	NSIC		1	1					
NOTES:			2	2					

AO-1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 25 ENCL 24



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101-1179 • 215/770-5151

Harold W. Keiser
Senior Vice President-Nuclear
215/770-4194

November 6, 1989

Director of Nuclear Reactor Regulation
Attention: Dr. W. R. Butler
Project Directorate I-2
Division of Reactor Projects
U.S. Nuclear Regulatory Commission
Washington DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION
REVISED RESPONSE TO BULLETIN 88-10
PLA-3286 FILE R41-2, R41-1A

Docket Nos. 50-387
50-388

Dear Dr. Butler:

In PP&L's response to NRC Bulletin 88-10 (PLA-3152 dated March 31, 1989), we indicated that five breakers would be replaced or tested prior to startup following the Susquehanna SES Unit 2 refueling outage which is currently in progress. Three of these breakers were installed in Unit 2 and have been replaced. The remaining two breakers are installed in a battery charger for the "E" Diesel Generator. Due to procurement delays, replacements for these breakers may not be available until January, 1990. PP&L is attempting to expedite delivery and will replace the breakers as soon as practicable. Continued operation has been justified. If you have any questions, please contact Mr. R. M. Harris at (215)770-7918.

Very truly yours,

H. W. Keiser

Attachments
Affidavit

cc: ~~NRC Document Control Desk (original)~~
NRC Region I
Mr. M. C. Thadani, NRC Project Manager-Rockville
Mr. G. S. Barber, NRC Sr. Resident Inspector-SSES
Mr. R. J. Bell, NUMARC
1776 Eye Street, N.W.
Suite 300
Washington DC 2006-2496

8911140023 891106
PDR ADOCK 05000387
Q PLC

IE21
1/1

