

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9211300396 DOC. DATE: 92/11/25 NOTARIZED: NO DOCKET #
 FACIL: 50-388 Susquehanna Steam Electric Station, Unit 2, Pennsylvania 05000388
 AUTH. NAME AUTHOR AFFILIATION
 STANLEY, H.G. Pennsylvania Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards LER 92-005-00 re isolation occurring when technicians were attempting to land lead in isolation logic & inadvertent grounding caused logic power fuse to blow.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+3
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES: Maxwell, G

05000388

	RECIPIENT ID CODE/NAME	COPIES	LTR	ENCL	RECIPIENT ID CODE/NAME	COPIES	LTR	ENCL
	PD1-2 LA	1	1		PD1-2 PD	1	1	
	RALEIGH, J.	1	1					
INTERNAL:	ACNW	2	2		ACRS	2	2	
	AEOD/DOA	1	1		AEOD/DSP/TPAB	1	1	
	AEOD/ROAB/DSP	2	2		NRR/DET/EMEB 7E	1	1	
	NRR/DLPQ/LHFB10	1	1		NRR/DLPQ/LPEB10	1	1	
	NRR/DOEA/OEAB	1	1		NRR/DREP/PRPB11	2	2	
	NRR/DST/SELB 8D	1	1		NRR/DST/SICB8H3	1	1	
	NRR/DST/SPLB8D1	1	1		NRR/DST/SRXB 8E	1	1	
	REG FILE 02	1	1		RES/DSIR/EIB	1	1	
	RGNI FILE 01	1	1					
EXTERNAL:	EG&G BRYCE, J.H	2	2		L ST LOBBY WARD	1	1	
	NRC PDR	1	1		NSIC MURPHY, G.A	1	1	
	NSIC POORE, W.	1	1		NUDOCS FULL TXT	1	1	
NOTES:		1	1					

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK. ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTR 32 ENCL 32

A04

R
I
D
S
/
A
D
D
S

R
I
D
S
/
A
D
D
S



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151


November 25, 1992

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 92-005-00
FILE R41-2
PLAS - 548

Docket No. 50-388
License No. NPF-22

Attached is Licensee Event Report 92-005-00. This report is being made pursuant to 10CFR50.73(a)(2)(iv), in that an unplanned ESF actuation occurred when the Residual Heat Removal System, operating in the Shutdown Cooling Mode, automatically isolated. The isolation occurred when technicians were attempting to land a lead in the isolation logic and an inadvertent grounding caused a logic power fuse to blow. The system was promptly restored and shutdown cooling was placed back in operation.


H.G. Stanley
Superintendent of Plant - Susquehanna

HL/mjm

cc: Mr. T. T. Martin
Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Mr. G. S. Barber
Sr. Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 35
Berwick, PA 18603-0035

500150

9211300396 921125
PDR ADOCK 05000388
S PDR

11/22