

ACCELERATED DOCUMENT DISTRIBUTION SYSTEM.

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9302190061 DOC. DATE: 93/02/09 NOTARIZED: NO DOCKET #
 FACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylvania 05000387
 AUTH. NAME AUTHOR AFFILIATION
 STANLEY, H.G. Pennsylvania Power & Light Co.
 RECIPIENT NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards updated LER 92-015-02 to rept discovery of addl fire barriers not meeting design specifications.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 5+1
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES	L	T	E	N	C	L	R	RECIPIENT ID CODE/NAME	COPIES	L	T	E	N	C	L	R	
	PD1-2 LA	1		1						PD1-2 PD	1		1						
	CLARK, R	1		1															
INTERNAL:	ACNW	2		2						ACRS	2		2						
	AEOD/DOA	1		1						AEOD/DSP/TPAB	1		1						
	AEOD/ROAB/DSP	2		2						NRR/DET/EMEB 7E	1		1						
	NRR/DLPQ/LHFB10	1		1						NRR/DLPQ/LPEB10	1		1						
	NRR/DOEA/OEAB	1		1						NRR/DREP/PRPB11	2		2						
	NRR/DST/SELB 8D	1		1						NRR/DST/SICB8H3	1		1						
	NRR/DST/SPLB8D1	1		1						NRR/DST/SRXB 8E	1		1						
	<u>REG FILE</u> 02	1		1						RES/DSIR/EIB	1		1						
	RGNI FILE 01	1		1															
EXTERNAL:	EG&G BRYCE, J.H	2		2						L ST LOBBY WARD	1		1						
	NRC PDR	1		1						NSIC MURPHY, G.A	1		1						
	NSIC POORE, W.	1		1						NUDOCS FULL TXT	1		1						

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTR 31 ENCL 31

A04



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

February 9, 1993

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 92-015-02
FILE R41-2
PLAS - 556

Docket No. 50-387
License No. NPF-14

Attached is Licensee Event Report 92-015-02, the second update to LER 92-015. This update is being provided to report the discovery of additional fire barriers (raceway wrap) not meeting design specifications. The previous update to this LER (i.e. 92-015-01) was provided for the same reason. Our inspection of all raceway fire barrier wrap is 98% complete with the only outstanding inspections remaining being components in Unit 1 which require a unit outage for access. Rework of the fire barriers is continuing.

TC Dalpino for

H.G. Stanley
Superintendent of Plant - Susquehanna

HL/mjm

cc: Mr. T. T. Martin
Regional Administrator, Region I
U.S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

Mr. G. S. Barber
Sr. Resident Inspector
U.S. Nuclear Regulatory Commission
P.O. Box 35
Berwick, PA 18603-0035

9302190061 930209
PDR ADOCK 05000387
S PDR

JEH 1/1