

APPENDIX A

NOTICE OF VIOLATION

Pennsylvania Power and Light Company
Susquehanna Unit 1 and 2

Docket No. 50-387/50-388
License No. NPF-14/NPF-22

During an NRC inspection conducted on July 19, 1994 - September 5, 1994, violations of NRC requirements were identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C, the violations are listed below:

- A. 10 CFR Part 50, Appendix B, Criterion XVI, "Corrective Actions," requires, in part, that in cases of significant conditions adverse to quality, measures shall assure that the cause of the condition is determined and corrective action taken to preclude repetition.

Contrary to the above, on March 4 and March 7, 1994, the licensee discovered that fire door 44 was blocked open and the required form NDAP-QA-0441 which authorizes and recognizes the condition was not completed contributing a significant condition adverse to quality. Additionally, prior to these occurrences, the licensee identified several instances where fire doors were blocked open without form NDAP-QA-0441 being completed. On July 20, 1994, the inspector discovered fire door 44 blocked open without the required approval. Corrective actions for these previous events did not preclude repetition in that the inspector identified, again, on August 23, 1994 that fire door 44 was blocked open without approval.

This is a Severity Level IV Violation (Supplement I).

- B. Technical Specifications 3.3.7.9, 3.7.6.2 and 3.7.7 require that continuous fire watches be established within one hour when fire detection and suppression systems are inoperable.

Contrary to the above, on August 2, 1994, at 9:31 p.m., continuous fire watches were not established within the required one hour following the determination that the Simplex Fire Protection System (fire detection and suppression system) was inoperable. Specifically, for at least 10 hours following the event, continuous fire watches were not implemented.

This is a Severity Level IV Violation (Supplement I).

Pursuant to the provisions of 10 CFR 2.201, Pennsylvania Power and Light is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555 with a copy to the Regional Administrator, Region I, and a copy to the NRC Resident Inspector at the facility that is the subject of this Notice, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the

violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. If an adequate reply is not received within the time specified in this Notice, an order or a Demand for Information may be issued to show cause why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to-extending the response time.

Dated at King of Prussia, PA
this 27th day of September 1994