

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9508080093 DOC.DATE: 95/08/03 NOTARIZED: NO DOCKET #  
 FACIL:50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylv 05000387  
 AUTH.NAME AUTHORITY AFFILIATION  
 STANLEY,H.G. Pennsylvania Power & Light Co.  
 RECIP.NAME RECIPIENT AFFILIATION  
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards LER 94-012-01, supplementing LER 94-012-00, in that condition prohibited by TS existed when continuous fire watches not established within one as result of inoperable fire suppression & detection equipment.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 145  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

05000387

	RECIPIENT		COPIES		RECIPIENT		COPIES	
	ID CODE/NAME	PD1-2 PD	LTR	ENCL	ID CODE/NAME	PD1-2 PD	LTR	ENCL
			1	1	POSLUSNY, C		1	1
INTERNAL:	ACRS		1	1	AEOD/SPD/RAB		2	2
	AEOD/SPD/RRAB		1	1	<u>FILE CENTER</u>		1	1
	NRR/DE/ECGB		1	1	NRR/DE/EELB		1	1
	NRR/DE/EMEB		1	1	NRR/DISP/PIPB		1	1
	NRR/DOPS/OECB		1	1	NRR/DRCH/HHFB		1	1
	NRR/DRCH/HICB		1	1	NRR/DRCH/HOLB		1	1
	NRR/DSSA/SPLB		1	1	NRR/DSSA/SPSB/B		1	1
	NRR/DSSA/SRXB		1	1	RES/DSIR/EIB		1	1
	RGN1 FILE 01		1	1				
EXTERNAL:	L ST LOBBY WARD		1	1	LITCO BRYCE, J H		2	2
	NOAC MURPHY, G.A		1	1	NOAC POORE, W.		1	1
	NRC PDR		1	1	NUDOCS FULL TXT		1	1

NOTES:

1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL  
 DESK, ROOM OWFN 5D8 (415-2083) TO ELIMINATE YOUR NAME FROM  
 DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED  
 TOTAL NUMBER OF COPIES REQUIRED: LTR 28 ENCL 28



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101-1179 • 610/774-5151

August 3, 1995

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION  
LICENSEE EVENT REPORT 94-012-01  
PLAS - 644 FILE R41-2

Docket No. 50-387  
License No. NPF-14

Attached is Licensee Event Report 94-012-01. This report supplements Licensee Event Report 94-012-00 which was made pursuant to 10CFR50.73(a)(2)(i)(B), in that a condition prohibited by Technical Specifications existed when continuous fire watches were not established within one hour to meet action statements required as a result of inoperable fire suppression and detection equipment.

  
H.G. Stanley  
VP - Nuclear Operations

RRW/dmd

cc: Mr. T. T. Martin  
Regional Administrator, Region I  
U.S. Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, PA 19406

Ms. Maitri Banerjee  
Sr. Resident Inspector  
U.S. Nuclear Regulatory Commission  
P.O. Box 35  
Berwick, PA 18603-0035

9508080093 950803  
PDR ADCK 05000387  
S PDR

JE22