

PRIORITY 1

(ACCELERATED RIDS PROCESSING)

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9509180304 DOC.DATE: 95/09/11 NOTARIZED: NO DOCKET #
 FACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylv 05000387 P
 AUTH.NAME AUTHOR AFFILIATION
 STANLEY, H.G. Pennsylvania Power & Light Co.
 RECIP.NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Forwards suppl LER to provide Commission w/info concerning potential blocking of ECCS suction strainers due to containment debris.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+7
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES: 05000387 I

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	
	PD1-2 PD	1 1	POSLUSNY, C	1 1	T
INTERNAL:	ACRS	1 1	AEOD/SPD/RAB	2 2	
	AEOD/SPD/RRAB	1 1	<u>FILE CENTER</u>	1 1	
	NRR/DE/ECGB	1 1	NRR/DE/EELB	1 1	1
	NRR/DE/EMEB	1 1	NRR/DISP/PIPB	1 1	
	NRR/DRCH/HHFB	1 1	NRR/DRCH/HICB	1 1	
	NRR/DRCH/HOLB	1 1	NRR/DRPM/PECB	1 1	
	NRR/DSSA/SPLB	1 1	NRR/DSSA/SPSB/B	1 1	D
	NRR/DSSA/SRXB	1 1	RES/DSIR/EIB	1 1	
	RGN1 FILE 01	1 1			
EXTERNAL:	L ST LOBBY WARD	1 1	LITCO BRYCE, J H	2 2	O
	NOAC MURPHY, G.A	1 1	NOAC POORE, W.	1 1	
	NRC PDR	1 1	NUDOCS FULL TXT	1 1	C
NOTES:		1 1			U

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM OWEN 5D8 (415-2083) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 28 ENCL 28



Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101-1179 • 215/774-5151

September 11, 1995

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 93-007-01
PLAS- 646 **FILE R41-2**

Docket No. 50-387
License No. NPF-14

Attached is Licensee Event Report 93-007-01, which is a supplemental report to voluntary report 93-007-00 which was submitted to provide the Commission with information concerning potential blocking of ECCS suction strainers due to containment debris. PP&L's corrective actions are identified in this supplement. Additional actions, if necessary, will be taken in response to further NRC generic communication on this issue.


H. G. Stanley
VP-Nuclear Operations

Attachment

RDK/toc

cc: Mr. T.T. Martin
Regional Administrator
U. S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

cc: Ms. Maitri Banerjee
Sr. Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 35
Berwick, PA 18603-0035

100071

9509180304 950911
PDR ADCK 05000387
S PDR

JE22