

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9803260123 DOC.DATE: 98/03/16 NOTARIZED: NO DOCKET #
FACIL: 50-388 Susquehanna Steam Electric Station, Unit 2, Pennsylv 05000388
AUTH.NAME AUTHOR AFFILIATION
KUCZYNSKI, G.J. Pennsylvania Power & Light Co.
RECIP.NAME RECIPIENT AFFILIATION
Document Control Branch (Document Control Desk)

SUBJECT: Forwards LER 98-001-00 re discovery that one secondary containment boundary had not been surveillance tested IAW TS requirement. LER submitted per 10CFR50.73(a)(2)(i)(B).

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+3
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	
	PD1-2 PD	1 1	NERSES, V	1 1	C
INTERNAL:	ACRS	1 1	AEOD/SPD/RAB	2 2	R
	AEOD/SPD/RRAB	1 1	FILE CENTER	1 1	
	NRR/DE/ECGB	1 1	NRR/DE/EELB	1 1	Y
	NRR/DE/EMEB	1 1	NRR/DRCH/HHFB	1 1	
	NRR/DRCH/HICB	1 1	NRR/DRCH/HOLB	1 1	
	NRR/DRCH/HQMB	1 1	NRR/DRPM/PECB	1 1	1
	NRR/DSSA/SPLB	1 1	NRR/DSSA/SRXB	1 1	
	RES/DET/EIB	1 1	RGN1 FILE 01	1 1	
EXTERNAL:	L ST LOBBY WARD	1 1	LITCO BRYCE, J H	1 1	D
	NOAC POORE, W.	1 1	NOAC QUEENER, DS	1 1	
	NRC PDR	1 1	NUDOCS FULL TXT	1 1	O

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTR 25 ENCL 25

George J. Kuczynski
General Manager-Susquehanna

Susquehanna Steam Electric Station
P.O. Box 467, Berwick, PA 18603
Tel. 717.542.3120 Fax 717.542.1949




March 16, 1998

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Mail Station P1-137
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 50-388/98-001-00
PLA - 0004871 FILE R41-2

Docket No. 50-388
License No. NPF-22

Attached is Licensee Event Report 50-388/98-001-00. This report is being made pursuant to 10CFR50.73(a)(2)(i)(B) in that it was discovered, during a procedural review for Improved Technical Specifications related activities, that one Secondary Containment Boundary had not been surveillance tested in accordance with the requirements of Technical Specifications 4.6.5.1.2a and 2b. The item had been inadvertently omitted from the surveillance procedure. The Limited Condition for Operation (LCO) for an incomplete surveillance, Technical Specification 4.0.3, was entered. The appropriate testing was promptly completed and the LCO cleared.


G. J. Kuczynski
General Manager - Susquehanna SES

Attachment

230023

cc: Mr. H. J. Miller
Regional Administrator
U. S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

cc: Mr. Kenneth M. Jenison
Sr. Resident Inspector
U.S. Nuclear Regulatory Commission
P. O. Box 35
Berwick, PA 18603-0035

9803260123 980316
PDR ADOCK 05000388
S PDR

1/1
IE22