

# CATEGORY 1

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9805130158      DOC. DATE: 98/05/04      NOTARIZED: NO      DOCKET #  
FACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylvania      05000387  
AUTH. NAME      ..      AUTHOR AFFILIATION  
KUCZYNSKI, G.J.      Pennsylvania Power & Light Co.  
RECIP. NAME      RECIPIENT AFFILIATION  
Document Control Branch (Document Control Desk)

SUBJECT: Forwards LER 98-005-00, describing event where util identified that IST of 9 check valves had not been completed within required frequency.

DISTRIBUTION CODE: IE22T      COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+3  
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES: 05000387

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
	PD1-2.PD	1 1	NERSES, V	1 1
INTERNAL:	ACRS	1 1	<del>AEOD/SPD/RAB</del>	2 2
	AEOD/SPD/RRAB	1 1	<del>FILE CENTER</del>	1 1
	NRR/DE/ECGB	1 1	NRR/DE/EELB	1 1
	NRR/DE/EMEB	1 1	NRR/DRCH/HHFB	1 1
	NRR/DRCH/HICB	1 1	NRR/DRCH/HOLB	1 1
	NRR/DRCH/HQMB	1 1	NRR/DRPM/PECB	1 1
	NRR/DSSA/SPLB	1 1	NRR/DSSA/SRXB	1 1
	RES/DET/EIB	1 1	RGN1 FILE 01	1 1
EXTERNAL:	L ST LOBBY WARD	1 1	LITCO BRYCE, J H	1 1
	NOAC POORE, W.	1 1	NOAC QUEENER, DS	1 1
	NRC PDR	1 1	NUDOCS FULL TXT	1 1
NOTES:		1 1		

NOTE TO ALL "RIDS" RECIPIENTS:  
PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LIST:  
OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL  
DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED  
TOTAL NUMBER OF COPIES REQUIRED: LTR 26 ENCL 26



George J. Kuczynski  
General Manager-Susquehanna

Susquehanna Steam Electric Station  
P.O. Box 467, Berwick, PA 18603  
Tel. 717.542.3120 Fax 717.542.1949



MAY 04 1998

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Mail Station P1-137  
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION  
LICENSEE EVENT REPORT 50-387/98-005-00  
PLA - 0004896 . FILE R41-2

Docket No. 50-387  
License No. NPF-14

Attached is Licensee Event Report 50-387/98-005-00. The report described an event where PP&L identified that the Inservice Testing (IST) of 9 check valves had not been completed within the required frequency. The IST Program requirements and test frequency are described in Technical Specification 4.0.5. Exceeding the required test frequency for IST components is reportable pursuant to 10CFR50.73(a)(2)(i)(B). The appropriate testing has been satisfactorily completed on Unit 2 and is scheduled for completion in the current Unit 1 Refuel Outage.

  
G. J. Kuczynski  
General Manager - Susquehanna SES

Attachment

cc: Mr. H. J. Miller  
Regional Administrator  
U. S. Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, PA 19406

cc: Mr. Kenneth M. Jenison  
Sr. Resident Inspector  
U.S. Nuclear Regulatory Commission  
P. O. Box 35  
Berwick, PA 18603-0035

9805130158 980504  
PDR ADOCK 05000387  
S PDR

1/1  
IE 22