

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9807280230 DOC. DATE: 98/07/23 NOTARIZED: NO DOCKET #
FACIL: 50-388 Susquehanna Steam Electric Station, Unit 2, Pennsylvania 05000388
AUTH. NAME AUTHOR AFFILIATION
KUCZNSKI, G. J. Pennsylvania Power & Light Co.
RECIP. NAME RECIPIENT AFFILIATION
Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 98-009-00 re automatic reactor scram that occurred following moisture separator high level condition & subsequent main turbine trip. Plant responded as expected, following scram, w/no ECCS initiations required.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+3
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
	PD1-2 PD	1 1	NERSES, V	1 1
INTERNAL:	ACRS	1 1	AEOD/SPD/RAB	2 2
	AEOD/SPD/RRAB	1 1	FILE CENTER	1 1
	NRR/DE/ECGB	1 1	NRR/DE/EELB	1 1
	NRR/DE/EMEB	1 1	NRR/DRCH/HICB	1 1
	NRR/DRCH/HOHB	1 1	NRR/DRCH/HQMB	1 1
	NRR/DRPM/PECB	1 1	NRR/DSSA/SPLB	1 1
	NRR/DSSA/SRXB	1 1	RES/DET/EIB	1 1
	RGN1 FILE 01	1 1		
EXTERNAL:	L ST LOBBY WARD	1 1	LITCO BRYCE, J H	1 1
	NOAC POORE, W.	1 1	NOAC QUEENER, DS	1 1
	NRC PDR	1 1	NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:


PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTR 24 ENCL 24

C
A
T
E
G
O
R
Y
1
D
O
C
U
M
E
N
T

George J. Kuczynski
General Manager-Susquehanna

Susquehanna Steam Electric Station
P.O. Box 467, Berwick, PA 18603
Tel. 717.542.3120 Fax 717.542.1949



July 23, 1998

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Mail Station P1-137
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 50-388/98-009-00
PLA - 0004957 FILE R41-2

Docket No. 50-388
License No. NPF-22

Attached is Licensee Event Report 50-388/98-009-00. This event was determined to be reportable per 10CFR50.73 (a)(2)(IV), in that an automatic Reactor SCRAM occurred, following a Moisture Separator high level condition and subsequent Main Turbine Trip. The plant responded as expected following the SCRAM, with no ECCS initiations required. There were no safety consequences or compromises to public health and safety as a result of this event.

G. J. Kuczynski
General Manager - Susquehanna SES

Attachment

cc: Mr. H. J. Miller
Regional Administrator
U. S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

cc: Mr. Kenneth M. Jenison
Sr. Resident Inspector
U.S. Nuclear Regulatory Commission
P. O. Box 35
Berwick, PA 18603-0035

9807280230 980723
PDR ADOCK 05000388
S PDR

1/1
IE 22